

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TPRES / ODRES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Val. or Market Value:

IDAO Accident Report

Consistent? Yes or No

SIA / PR Sent

Consistent? Yes or No

Est. Repairs:

days

Res.: Yes or No

Sum Sum:

%

3 Vol.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLE 4491X Yr Regn: 22/7/16

Type: M.G. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Citroen 24 Pk 4550

cc

1560

Colour:

White

A/O:

Insured / Std / NI / H

Sp. Reading

105731

TIRadio: Insured / Std / NI / H

Eng/No:

On/No:

V F 730 B H Z J F T 890014

Gen. Cond: Good / Fair / Poor / Bught

Steering: Inorder / Jammed / Locked / Burnt or

Brake: Inorder / Jammed / Locked / Burnt or

Mod: Nil / 3/4 in / STD A/Rim or

Tyre Size:

Ft

185/55 R 15

Ri

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A.

21/12/21

D.O.A.

27/12/21

Survey held at

Auto Insure

Des. of Damages: FR / Rear / CIS / N/S / VIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-53K

me/Time, File, Resolv.



Prell. Report



Final Report

me/Time, File Return to?

Days Of Repair:

Resurvey No. of Trips:

Survey Fee:

Transportation

S. P. S. SI

Friction

Quiver

Vertical

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Vehicle and (\$



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLE4491X (SIEW)
Your Ref: YN6719B

Date: 27-Oct-21

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

LONPAC INSURANCE BERHAD

300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Assessed Vehicle No : SLE4491X
Car Make and Model : CITROEN C4 PICASSO 1.6 BLUEHDI EAT6
Date of Accident : 21-Oct-21
Date of Assessment : 27-Oct-21

We have carried out a physical assessment of SLE4491X at our workshop Auto Insure Pte Ltd sustained damages to the RH portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : L/S
Adjusted Amount : \$ 3,700.00
Est. Repair Days : 3



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SLE4491X

Your Ref: YN6719B

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	<u>PARTS REPLACEMENT - LIST ITEMS</u> REAR DOOR RH / <i>07</i>		\$ 2,529.96
			SUB TOTAL	\$ 2,529.96
			LESS 15%	\$ 253.00
			TOTAL AMOUNT	\$ 2,276.96

Our Ref: SLE4491X

Your Ref: YN6719B

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR DOOR SEALANT RH / <i>17/1</i>		\$ 50.00
2	1	REAR DOOR STICKER RH / <i>17/1</i>		\$ 200.00
			SUB TOTAL	\$ 50.00
			TOTAL PARTS COST	\$ 2,326.96

Our Ref: SLE4491X

Your Ref: YN6719B

Your Ref: YN6719B

S/NO	DESCRIPTION	EST. BY WORKSHOP	
	<u>LABOUR & PAINTWORK</u>		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 200	300.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 30	100.00
3	TO REMOVE & REFIT REAR DOOR MECHANISM RH	\$ 50	150.00
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 200	400.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 30	50.00
6	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$	50.00
7	TO VACUUM, WAXING & CLEAN	\$ 30	60.00
8	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 30	50.00
TOTAL BEFORE GST		\$	3,486.96
GST 7%		\$	244.09
TOTAL (PARTS & LABOUR):		\$	3,731.05

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$ 3,700.00** for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

Steve (LKK)
27/10/11, 12.00pm

MR PL
2 dys
L/S
Ry KL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/10/2021 17:32 (SGT)
Date of Accident 21/10/2021 12:30 (SGT)
Exact Location of Accident 134 Marsiling Rd, Block 134, Singapore 730134
Additional Location Information OPEN CAR PARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLE4491X

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner TAN BAN THONG
NRIC No SXXXX708C
Email Address tanbanthong@gmail.com
Mobile Phone No (Phone) +65-83223200
Alternative Phone No +65-83223200

VEHICLE PARTICULARS

Manufacturer Citroen
Model C4
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1560

INSURANCE COMPANY

Name of Insurance Company Auto & General Insurance (Singapore) Pte. Limited.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number P10394671R01
Cover Note Number -

DRIVER

Name of Driver TAN BAN THONG
NRIC No SXXXX708C

Date Of Birth 24/05/1962
 Occupation Indoor
 Date Of Driving Pass 12/06/1986
 Driving experience 35 YEARS AND 4 MONTHS
 Gender Male
 Mobile Number
 Alt. Phone Number (Phone) +65-83223200
 Email Address +65-83223200
 Address tanbanthong@gmail.com
 Address complement BLK 134 MARSILING ROAD
 Postcode
 Is the driver the policyholder? 730134
 If No, Relationship of the Driver with the Insured Yes
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver No
 Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 0
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

MY VEHICLE WAS PARKED AT THE OPEN CAR PARK OF BLK 134 MARSILING ROAD ON 20/10/2021 ABOUT 2045HRS. ON 21/10/2021 AT ABOUT 1230HRS, I RETURN BACK TO MY VEHICLE, I REALISED THAT MY REAR RIGH THAND SIDE WAS DAMAGED AND DISCOVER A NOTE LEAVE ON MY WINDSCREEN STATE THAT VEHICLE B HAD COLLIDED ONTO MY VEHICLE. I THEN CONTACT THE COMPANY AND THE COMPANY TOLD ME TO CLAIMS THEIR INSURANCE.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN6719B
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Commercial vehicle
 Name of Driver -
 Contact Number -

SKETCH PLAN

Refer to statement

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was parked at the open car park of Bit 134 Marsiling Road on 20/10/2021 about 2045hrs. On 21/10/2021 about 1230hrs, I return back to my vehicle, I realised that my rear right hand side was damaged and I discover a note leave on my windscreen state that vehicle B had collided onto my vehicle. I then contact the company and the company told me to claims their insurance.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

bully
Policyholder's Signature
Date & Time:

bully
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Q188340 SketchPlanForm_V3

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	708C
Vehicle Details	
Vehicle No.:	SLE4491X
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Oct 2021
Vehicle Make:	CITROEN
Vehicle Model:	C4 PICASSO 1.6 BLUEHDI EAT6
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	10JBHD3030901
Chassis No.:	VF73DBHZTFJ890014
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$23,342.00
Original Registration Date:	22 Jul 2016
First Registration Date:	22 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$9,679.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jul 2026
PARF Rebate Amount:	\$6,775.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$24,745.00
Total Rebate Amount:	\$31,520.00

The information contained herein is correct as at 27 Oct 2021

OK