

MOTOR SURVEY ASSIGNMENT

**Date** 27/10/2021 **Our Ref No.** D21002757MFBP

Accident Date 26-09-2021 Claim Type Third Party

Insured Vehicle SBS6503C Third Party Vehicle SLV1508M

Survey Location MG SOLUTION PTE LTD Contact Person MS HONG

23 KAKI BUKIT AVE 4 SOUTH

WING #04-01 VICOM

**INSPECTION CENTRE S415933** 

**Contact No.** 62431373 **Fax No.** 0

Survey Type Without Prejudice

Appointed LKK AUTO CONSULTANTS PTE LTD

Surveyor LKK AUTO CONSULTANTS PTE LTL

Contact Person Fax No. 68416315

Contact Number 62563561

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**Encl. Accident Reports** 

Cc: Workshop MG SOLUTION PTE LTD Attention MS HONG

Officer Incharge ESTHER

## **IMPORTANT NOTE**

Kindly submit the survey report by **email only** to <u>surveyor@msfirstcapital.com.sg</u> within 14 days for survey assignment and 7 days for re-inspection.