

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident	27/10/2021 10:16 (SGT) 26/10/2021 12:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TAMPINES MALL LOADING BAY
Country/State of Loss	Singapore

Additional Location Information Country/State of Loss	TAMPINES MALL LOADING BAY Singapore
DETAILS OF	OWN VEHICLE
Vehicle Registration Number	GBD9141Y
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No	Yes B2H TRADING PTE LTD 201111670W ZKEE@HOTMAIL.COM (Phone) +65-93629820
Alternative Phone No VEHICLE PARTICULARS	+65-93629820
Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC	Toyota Hiace - Employment No - Claiming third party Commercial vehicle Auto 2989
INSURANCE COMPANY	
Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number	NTUC Income Insurance Co-operative Ltd Comprehensive No 5122803717 05/07/2021 - 04/07/2022
DRIVER	

TOH BOON TEONG

S1339566G

NRIC No

Name of Driver

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	13/09/1958 Outdoor 15/09/1978 43 YEARS AND 1 MONTH Male (Phone) +65-97595353 - ZKEE@HOTMAIL.COM BLK 566 WOODLANDS DRIVE 53 #03-57 - 730556 No Employee No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Side Swipe Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No 2 No - Yes 1
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No
CIRCUMSTANCES OF ACCIDENT	
REFER TO SKETCH PLAN	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No No

DETAILS OF OTHER VEHICLE PROPERTY 1

GBE3258D Vehicle Registration Number Toyota Vehicle Manufacturer Dyna Vehicle Model Vehicle Variant Vehicle Colour Commercial vehicle Vehicle Category LIU YONGHUA Name of Driver Passport No/FIN G2208271Q (Phone) +65-86964655 Contact Number Address

Address complement	-
Postcode	-
nsurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	1

INCOME MOTOR SERVICE CENTRI		Report Date & Start Time:	27 10 2021 - 09.38
Report Not MT	D.O.A <u>26/10/2021</u> Time: 12:30 hrs	Vehicle No GBD9141Y	Reporting Type:

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents{including their lawyers/law firms}, which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

J.

27-10/21 9:38

Policyholder's Signature / Date & Time


27/10/21 / 9:38

Driver's Signature (If driver is not the policyholder) / Date & Time

Ganesh (S993561) Customer Care Executive Motor Service Centre

Witnessed by Reporting Centre Peronnel

SKETCH PLAN



TAMPINES MALL LOADING BAY

Vehicle A: GBD9141Y

Vehicle B: GBE3258D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was reversing to loading bay, while reversing vehicle B suddenly reversed even I honked at him but driver be still continue to reverse and collided to my vehicle left side. After which both drivers alighted to assess the damage, took some photos and exchange particulars. No one was injured in this accident.

Declaration

I/We declare the for are true in every respect.

27/10/21 / 9:38

27/10/21 / 9:38

Motor Service Centre

ustomer Care Executive

Witnessed by Reporting Centre Personnel