

Submitted 28.10.2021

Part replaced

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2285269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 155941
Fax: 64747770

260, Esplanade Road
East Coast Centre
Singapore 438160
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64766601 (AfterSales)
64766624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 59873
Date Estimated : 27/10/2021
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Khoe Hong Oan
37 Greenfield Drive

Singapore 457941

- ACCOUNT - 158

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD125E	WBA7E02070G245475	25/06/2018	730Li	23814

DESCRIPTION	VALUE
To replace front bumper, bonnet, right front fender, right headlight support including to knock out dented area caused by the accident <i>880 x 3</i>	<i>2550</i> 4,250.00
To respray front bumper, bonnet and right front fender	<i>3060</i> 3,221.00
To carry out body cavity preservation (2X)	<i>224</i> 236.00
To replace right headlight.	<i>456</i> 481.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	<i>168</i> 177.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	<i>168</i> 177.00
Sundries.	150.00

Total Labour 1: **8,692.00**

DESCRIPTION	QTY	PRIC	VALUE
# FRT RH SIDE PANEL ALUMINIUM	1	1,304.95	1,304.95
# FRT RH 1 SIDE PANEL BRACKET	1	35.30	35.30
ALUMINIUM BONNET	1	3,043.10	3,043.10
EXPANDING RIVET	12	0.50	6.00
FRT BUMPER BOTTOM CARRIER	1	483.45	483.45
# VERTICAL CONNECTION LH	1	18.30	18.30
# VERTICAL CONNECTION RH	1	18.30	18.30
# RH GUIDE BOTTOM	1	59.10	59.10
# GUIDE TOP RH	1	59.10	59.10
# RH SUPPORT FOG LAMP	1	54.50	54.50
# IMPACT ABSORBER TOP	1	91.30	91.30
# FRT BOTTOM IMPACT ABSORBER	1	127.80	127.80
FRT BUMPER CARRIER	1	879.00	879.00
RH PROTECTIVE STRIP BOTTOM	1	76.45	76.45

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59873
Date Estimated : 27/10/2021
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD125E	WBA7E02070G245475	25/06/2018	730Li	23814

DESCRIPTION	QTY	PRIC	VALUE
DESCRIPTION			
RH PROTECTIVE STRIP TOP <i>CNT (change)</i>	1	76.45	76.45
BUMPER GUARD CENTRE	1	76.45	76.45
FRT BUMPER PANEL PRIMED (PDC/PMA) <i>00</i>	1	1,620.95	1,620.95
# FRT BUMPER TOWING LUG COVER <i>BR</i>	1	57.70	57.70
MIDDLE GRILLE AIR INLET (PURE EXCEL?)	1	83.60	83.60
# RH GRILLE AIR INLET (PURE EX <i>CNT</i>)	1	100.30	100.30
# RH INSULATED	1	101.25	101.25
FRT RH GRILLE (PURE EXCELLENCE) <i>CNT</i>	1	282.85	282.85
AIR FLAPS TOP	1	373.35	373.35
EMBLEM GROMMET <i>nk</i>	2	0.85	1.70
REAR PLAQUE 82MM <i>nk</i>	1	71.95	71.95
EXPANDING RIVET D=8MM	10	1.10	11.00
AIR DUCT BOTTOM	1	100.85	100.85
# RH HEADLIGHT MOUNTING	1	221.85	221.85
# FRT RH WHEEL ARCH COVER FRT	1	145.45	145.45
COVERING CROSS MEMBER (ECE)	1	29.25	29.25
RH BRAKE AIR DUCT	1	52.05	52.05
AIR DUCT RADIATOR TOP	1	78.10	78.10
# AIR DUCT RADIATOR BOTTOM	1	78.10	78.10
# Air duct brake, wheel arch R	1	52.05	52.05
RH COVER BOTTOM	1	71.60	71.60
# SEAL ENGINE HOOD FRT	1	40.05	40.05
RH HEADLIGHT LED AHL HIGH (ICON LIG <i>CNT</i>)	1	5,886.55	5,886.55
RH FOG LAMP LED	1	473.70	473.70
ULTRASONIC SENSOR BLACK	2	251.20	502.40
DECOUPING RING PDC TORQUE CONVERTER <i>nc</i>	2	5.15	10.30

Total Parts : 16,856.50

Steve CLKK
8/11/21, 9.30am

00- M1 AL
EXEN- \$1000
PIP

by BL sy
5 days

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company



Knownledged by Repairer

Signature:

Date:

Labour 1	:	8,692.00
Parts	:	16,856.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,788.40
Grand Total	:	27,336.90

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/10/2021 19:12 (SGT)
Date of Accident	26/10/2021 18:02 (SGT)
Exact Location of Accident	Tanjong Rhu, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDD125E
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KHOE HONG OAN
NRIC No	S2183233B
Email Address	KHOEHO@GMAIL.COM
Mobile Phone No	(Phone) +65-98153466
Alternative Phone No	+65-98153466

VEHICLE PARTICULARS

Manufacturer	BMW
Model	730LI LED NAV HUD SR RCP
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	Lonpac Insurance Bhd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	Z21VP05029264
Cover Note Number	-

DRIVER

Name of Driver	KHOE HONG OAN
NRIC No	S2183233B

Date Of Birth	25/12/1962
Occupation	Indoor
Date Of Driving Pass	23/04/1980
Driving experience	41 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98153466
Alt. Phone Number	+65-98153466
Email Address	KHOEHO@GMAIL.COM
Address	37 GREENFIELD DRIVE
Address complement	-
Postcode	457941
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

-

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMH324U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

LICENSE PLATE: 3DD1258	ACCIDENT DATE & TIME: 6.42 PM 26/10/21
CONTACT NUMBER: 98153466	E-MAIL ADDRESS: khueho@gmail.com
LOCATION: TANSUNG KHU RD.	

I was exiting the car park (S'PORE SWIMMING CLUB) and making a right turn toward Meyer. Did not realise an incoming car (SMH324U) making his right turn into the carpark at the same time. My attention was focused on incoming behind his car (not realizing he stop his car at the turning) resulting in the impact.


NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.

Please state:

☒ Claim Own Policy ☐ Claim Third Party ☐ Claim OD/TP at other workshop ☒ Reporting Only

Declaration

We declare the foregoing particulars are true in every respect.


 27/10/21
 Policyholder's Signature / Date & Time 12.35 PM

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel 