## COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA7170X

Make Model

: HYUNDAI

: IONIQ(G3)

Date: 18/10/2021

Insurance: NTUC

MVA: MS. LOKE YY

			MVA: MS, LO	UNE TY	
2ty	Parts Description / Labour	Туре	Unit Price	Amount	
	1 FRT DOOR RH			\$1,797.20	
	1 FRT DOOR GEAR/ REGULATOR RH			\$750.40	
	1 FRT DOOR INNER LOCK RH			\$385.60	
	1 FRT DOOR KEY LOCK SET RH			\$353.5Q	
	1 FRT DOOR OUTER HANDLE RH			\$234.8Q	
	1 FRT DOOR POWER MOTOR RH			\$689.20	
	1 FR DOOR PROTECTOR RH			\$186.20	
	1 FRT DOOR GLASS RH			\$215.20	
				\$2.0.20	
	SUB TOTAL			\$4,612.10	
	LESS 20%	6		\$922.42	
	DISCOUNTED TOTAL	_		\$3,689.68	
	FRT DOOR COMFORTDELGRO LOGO STICKER RH			\$75.00	
				\$75.00	
	l about Ch				
	Labour Charge			\$700.00	
	PANEL BEATING			\$700.00 \$300.00	
	SPRAY PAINTING CHARGE				
	TRANSFER OF DOOR			\$120.0Q \$60.00	
	CHECK WIRING				
	TOTAL LABOU	₹		\$1,180.00	
	FOTHATE TOTA			\$4,944.68	
	ESTIMATE TOTA	4		<del>\$4,544.00</del>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Throng/hhauto-lom
87235769
18/10/2/ 1730
P/P hfr paint photo
2 clays wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: