

NEW - (PIP)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 18.10.2021
Time: 15:23:13
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305491253
REGN NO : SHC7967D ✓
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 18.10.2021 11:30
ACCIDENT DATE : 18.10.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2292-G COVER-FR BUMPER#	1	430.90	20.00	344.72	✓DT
0002 04-01-0101-0111-G BUMPER COVER CLIP REAR front	10	22.00	20.00	17.60	✓nec
					SUB-TOTAL : 362.32

JOB NATURE

0000 PB PANEL BEATING	400.00	350
0001 SP SPRAYPAINT CHARGE	300.00	250
		SUB-TOTAL : 700.00

TOTAL : 1,062.32

Juman!

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Thuan @ Lkh auto .com
82235769
18/10/21 1745
PIP qst bfr paint photo
2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: