

REF: CS/LAW21011081/Dqf3

Special Instruction:

L/SUM : \$ 16,800.00

From (Person): TEO YI XUAN of LAW ASSIGNMENT (Office) Date/Time: 29/10/2021 1:19 PM

Third Parties:

Estimated Cost: _____ Bill to: _____

Claimant:

Surveyor:

Workshop: N-51 AUTOMOTIVE PL

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SGH 4547M

Insured: SJQ 2187Z

at Workshop m/s N-51 AUTOMOTIVE PL

Tel: 6744 0510 / 98575300

of 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921

Policy No: CLE-atv-INS-N63-110857-19/SN

Claim No: 2021000027.NTUC (mpd)

Sum Insured:

Excess:

Make of Veh:

D.O.A. 04/08/2018

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red \$ ____/____%; Original 8 days)

Date/Time: _____ Submit Final Fig _____, ____ days (Red \$ _____/____%; Original ____ days)

[illegible]

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____