



Claim	S1M03L0K
Reference	CS3/ASM21011089/Euy3e2 
Loss Date	26 October 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	29 Oct 2021 12:57:07 PM
Request Date	29 October 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident

SLK7821B

Vehicle
Registration #

Make

TPVD

Model

TBC

Service Address

’, ’

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Additional Instructions

- Messages2
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes 2

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRIT TP PDF.pdf.pdf	Other	Other	do not reply	
 ASM-LKKInvoice-AC2107554.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	5 November 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	5 November 2021

FAQ English (SG) Elaine Kuan			SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...	ce	Photos	LKK AUTO CONSULTANTS PTE LTD (TP) 5 November 2021
	AXA Immediate Advice - SLK 7821B.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 November 2021
	SLK7821B INSPECTION PHOTOS.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	1 November 2021
	TP GIA.pdf.pdf	Reports & Statement	GIA Report	LOH Cynthia	29 October 2021
	REPLY FROM SOLICIOTR.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	29 October 2021
	SHD3673Y INS GIA.pdf.pdf	Legal	Others	KUMAR Shailendra	29 October 2021
	PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	29 October 2021

FAQ English (SG) ▼ Elaine Kuan ▼			SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...	Others	KUMAR Shailendra	29 October 2021