

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Vehicle No.: SH6054M
 Make : TOYOTA - 20.09.2017
 Model : PRIUS
 DOA : 20/10/2021

Date : 21.10.21
 Insurance: CHINA
 MVA : CHIANG /
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70
1	REAR TRUNK			\$1,126.60
1	REAR TRUNK COVER TRIM			\$254.40
1	REAR TRUNK LID LOGO (PRIUS)			\$52.90
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$60.80
1	TRUNK LID GLASS W/MOULding UPPER			\$1,778.30
1	TRUNK LID GLASS W/MOULding LOWER			\$1,569.70
1	REAR BUMPER			\$458.60
1	REAR BUMPER UNDER COVER			\$552.60
10	REAR BUMPER CLIP		\$2.20	\$22.00
2	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40
2	REAR BUMPER UNDER SIDE COVER /RH		\$232.00	\$232.00
1	REAR BUMPER UNDER COVER CENTRE			\$252.00
1	TAIL LAMP UPPER RH			\$557.90
1	TAIL LAMP LOWER RH			\$548.40
1	REAR SMART KEY ANTENNA			\$312.00
1	REAR BUMPER TOWING COVER			\$82.70
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$318.80
SUB TOTAL				\$9,369.20
LESS 25%				\$2,342.30
DISCOUNTED TOTAL				\$7,026.90
1	REAR TRUNK LID APPS STICKER			\$40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$60.00
1	REAR NUMBER PLATE W/HOLDER			\$50.00
1	REAR BUMPER REVERSE SENSOR			\$135.70
LKK Auto Consultants hence notify the Repairer of the following:				
• To resurvey before/after spray painting				
• To display damaged part(s) during resurvey				
• Parts prices are subject to confirmation				
• Third party survey is on a "Without Prejudice" basis				
• No illegal modification(s) is allowed				
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
Acknowledged by Repairer				
Signature:				
Date:				
TOTAL LABOUR				\$1,960.00
ESTIMATE TOTAL				\$9,272.60

Labour Charge

Panel Beating

Spray Painting Charge

Wiring Charge

Tuff Kote

Remove/Refix Reverse Sensor

thuan@lkhauto.com
 87235769

21/10/21 1600

1/5 after repair photo

3 days swp

Date/Time: 21.10.2021 08:49

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO305491476

CUSTOMER

NAME: COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO: 7010045
ADDRESS: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

COUNT CARD NO.

REGN NO.:

SH 6054M

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)20.

DATE/TIME IN
10.2021 15:50

YR OF MANU.

20.09.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU903564050

COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 20.10.2021

NATURE: 3P 20.10.2021

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

SH 6054M

CHIANG

Vehicle No.:

SH 6054M

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard