	CY/AIG	2101 1105/193
		GNMENT
	From Cate.	Veh No: SHB 88117 VI ROGA: 9/5/14
	QD/TP/WS/JP RES/OD RES/EVA/INV/MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / 732) Prime Mover /
	To Inspect Vehicle No:	Truck / Traller or
	and designation of the same of the contract of the	Moko: Hyundai vovig o.c 1580
	Ul Workshop m/s	Colour Silver NC: Insured/Std/III/NA
	bl.	Sp. Reading 78/404 . T/Radio: Insured / Std / NI / NA
	Insured:	Eng/No:
	Policy No	CNO: MMHC851CUHU179685
	Claims No.	Gen. Cond: Codd / Falr / Poor / Burnt
	Sum Insured: Excess:	Sleering: Ina@r / Jammed / Leaked / Burnt or
	(Client's Record)	Brake: India / Jammed / Leaked / Burnt or
	Make of Veh:	Modi: NII / SIRID / STD A/RIM or
	(Policy Condition)	Tyre Size: F: 145/65/15
	Remark: The veh had commenced Its N/S O/S	R: 195/65 R15
	repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MICY OHTSU / PIR / SUMI /
	Bal. or Market Value:	TOYO/YOKO or
		<u>Fron</u> <u>Roar</u>
	IDAC Accident Rport: Consistent? : Yes or No	R/Bal. S mm R/Bal. S mm
	GIA / PR Seen: Consistent?; Yes or No	L/Bal, 5 mm L/Bal. 5 mm
	Est. Repairs. 3 days Ros.: Yos or No	D.O.A. 79/10/21 D.O.I. 29/16/21 1700
	Lum Sunt: 3 Val.: Yos or No	Survey held al Mrimicr
	CA / REV / REP. / 24 HRS	Des. of Damagos : Frt / Rear O/S / N/S / U/C / Rooflop or
	Vehicle: IN / OUT Date Person Contacted	
	Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
	16 hate: 29882	
	· · · · · · · · · · · · · · · · · ·	
	Case/Time_Fla Pass 6/7 Proll. Report D	ays Of Repair:
	i) : Final Roport R	esurvey No. of Trip: Survey Fee:
	Data/Time File Return 107	Trussperation;
,	Add Fee:	: Site Insp (\$ )S+RSSI .
10		: Interview (\$ ) Ftinlos
7	Seport Folias :	Tech, Inva (\$ ) Oliver
V.	Lucip Sina (I.B.): 12	: Weel and 18
7	A STATE OF THE STA	Section 1

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

29-Oct-21

ESTIMATE	REPAIR BILL FOR HYUNDAI	IONIQ REGN NO: SHB 8811 T		
1 pc				
1 pc	Tailgate		\$	2,480.40×V
1 pc	Emblem "Hyundai"		\$	28.0Q/nx<
*	Emblem "Hybrid"		\$	24.30 JN (C
1 pc	Emblem "Ioniq"		\$	31.3Q/MIC
2 pcs	Rear n/s & o/s tail lamps		\$	725.20 X UC
1 pc	Rear bumper		\$	459.40 J (Ur
1 pc	Rear bumper reinforcement		\$	294.80 ^-
2 pcs	Rear bumper reinforcement n/s 8		\$	20.00 <b>Mubic</b>
1 pc	Rear bumper reinforcement cent	re lower bracket	\$	15.00
2 pcs	Rear bumper n/s & o/s stay		\$	276.20 X SUC
2 pcs	Rear bumper n/s & o/s side brack		\$	66.20 Jane 4 SUC
1 pc	Rear bumper lower moulding cer	ntre	\$	216.50) SCV
1 pc	Rear bumper lower cover		\$	47.50 / DIS
1 pc	Rear bumper cap hook		\$	9.10/(4+
2 pcs	Rear bumper n/s & o/s reflector		\$ \$	63.80 XSVC
	1	1/// 1 1 0 - 1 1 - 1 - 1 - 1 - 1 - 1 - 1	\$	4,757.70
		LKK Auto Consultants hence notiess 20% the Repairer of the following:	\$	951.54
C/N		To resurvey before/after spray painting	\$	3,806.16
<u>S/N</u>		<ul> <li>To display damaged part(s) during resurvey</li> </ul>		/ -
1 set	Rear bumper clips	Parts prices are subject to confirmation     Third parts suppose in on a "Without Projection" had a	\$	48.00/nec
1 set	Reverse sensor	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed	\$	280.00/(UF
1 pc	Rear number plate with casing	<ul> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul>	\$	50.00/(ra
1 set	Tailgate stickers	Acknowledged by Repairer	\$	100.00 / N LC/
		Signature:		
	Sundry	Date:	\$	50.00 X SVC , '
Thurn @/ Hourto. Can	To check wiring		\$	50.00 70
Thurnel Humbo. 6 82235769 29/10/21 / 700	To dismantle/refit rear tailgate wii tailgate	ndow glass onto new	\$	120.00 XNN
		ensor to new bumper and	\$	120.00 30
PIP her paint phof 3 clays up	→ To dismantle / refit the inner garn trims, cushion seat, carpet, etc to		\$	180.00 <b>KQ</b> 40
3 clays up	To labour charge for dismantle ar damaged parts. Including knock-reshape and adjust of the end pa	out, straighten, repair,	\$	850.00 360
	To putty and spray painting on reabumper lower cover (Black), tailgo		\$	800.00 360
	To apply rustproofing on the repa	ired and replaced panels.	\$	120.00 20
			\$	6,574.16

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

#### > Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Vehicle Make:

Owner ID Type: Company
Owner ID: 975H

Vehicle Details

 Vehicle No.:
 SHB8811T

 Vehicle to be Exported:
 No

 Intended Deregistration Date:
 01 Nov 2021

Vehicle Model: AE IONIQ HEV 1.6 DCT

Primary Colour: Silver
Manufacturing Year: 2018

Engine No.: G4LEJU156318

 Chassis No.:
 KMHC851CVKU129685

 Maximum Power Output:
 103.6 kW (138 bhp)

Open Market Value:\$25,279.00Original Registration Date:09 May 2019First Registration Date:09 May 2019

Transfer Count: 0

Actual ARF Paid: \$12,391.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 May 2027
PARF Rebate Amount: \$9,293.00

Intended COE Rebate Details
COE Expiry Date: 08 May 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

 COE Period(Years):
 8

 PQP Paid:
 \$22,309,00

 COE Rebate Amount:
 \$15,389,00

 COE Rebate Amount:
 \$15,389.00

 Total Rebate Amount:
 \$24,682.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Nov 2021

ОК

HYUNDAI

SP0121AT0002 / PREMIER AUTOMOTIVE SERVICES PTE LTD ENTRY DATE & TIME: 29/10/2021 13:00 (SGT) SUBMITTED BY: NG BOON KAI VERSION: 1 (29/10/2021 13:00 (SGT))

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies

5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission Date of Accident **Exact Location of Accident** 

Additional Location Information Country/State of Loss

29/10/2021 13:00 (SGT) 29/10/2021 10:55 (SGT)

Near 218 Jln Kayu, Singapore 799440

JALAN KAYU SLIP ROAD TOWARDS SENGKANG WEST WAY

Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SHB8811T

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

**Email Address** 

Mobile Phone No Alternative Phone No.

Yes

PREMIER TAXIS PTE LTD

2XXXXX975H

CLAIMS@PREMIERTAXI.COM

(Phone) +65-91550072 (Office) +65-62148880

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

Hvundai

Ionia

Employment

No - Claiming third party

Taxi Auto

1700

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number NTUC Income Insurance Co-operative Ltd

ThirdParty Yes

5107202885-02

DRIVER

Name of Driver NRIC No

TAN MAH HO SXXXX695H



Date Of Birth Occupation Date Of Driving Pass Driving experience

Gender Mobile Number Alt. Phone Number Email Address

Address

Address complement

Postcode

is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER SKECTH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Was there any audio recorded?

22/08/1956 Outdoor 28/06/197A

45 YEARS AND 4 MONTHS

(Phone) +65-94566333

CLAIMS@PREMIERTAXI.COM

BLK 444, JURONG WEST AVENUE 1 #08-782

640444 No

Hirer No

Collision - Head to Rear

Clear Dry

No

2 Yes No Yes

No

No

No

Yes No No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer

Vehicle Model Vehicle Variant

Vehicle Colour Vehicle Category

Name of Driver NRIC No

Contact Number

Address

SFH6522H Mercedes

White Private car

GERMAINE LEE YING TING

SXXXX666Z

(Phone) +65-94243458



#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful insrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GA Records Management Centre established by the General insurance Association of Singspore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Aman Dan 39/10/2021 1235pm

Driver's Signature (if driver is not the policyholder) / Date & Time

Wanessed by Reporting Centre Personnel

1

Sketch Plan

A = SAB 8811T B = SFH 6522H

Jaka Kayn

Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

# INJURED PERSONS DETAILS

### INJURED 1

Name of injured person

Gender

Phone No Address

Address Complement

Post Code

Approximate Age Years Old

Injuries Sustained

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

TAN MAH HO

Male

(Phone) +65-94566333

DRIVER FELT UNCOMFORT, WILL SEEK DOCTOR

Yes No

Accident report SP0I21AT0002

Plant Mel Alling	
The Property of	
/	1
	- Marining (Adaption of the Control
J	D
	PROPERMINANTAL
	7
	Maintelaction
	er Stantisch zu der Greine der Gr

### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

# Describe Circumstance of the Accident


ON 29/10/2021 @ 10 59HRS. I WAS DRIVING MY TAXI - SHB8811T, TRAVELLING ALONG JUN KAYU INTO SENGKANG

I WAS SLOW DOWN AND COMPLETE STOPPED AT SLIP ROAD FOR GIVING WAY TO ONCOMING VEHICLE FROM THE MAIN ROAD SUDDENTLY, VEHICLE B (SPH6522H-MERCEDES) WHICH WAS BEHIND MY VEHICLE UNABLE STOP IN TIME

DUE TO THE IMPACT, MY TAXI WAS DAMAGE ON THE REAR PORTION & VEHICLE B WAS DAMAGED ON THE FRONT

NO PASSENGER ONBOARD BOTH VEHICLES

VIDEO CAPTURED





**Enquire Vehicle Registration Details** 

### **Owner Particulars**

NRIC/Passport

/Company Cert

200304975H

No.:

Owner ID Type:

Company

Owner Name:

PREMIER TAXIS PTE. LTD.

Registered

Address:

23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443

Mailing Address:

Birth Date:

## Vehicle Particulars

Vehicle No.:

SHB8811T

Previous Vehicle

No.:

Effective Date of

Ownership:

09 May 2019

Original Regn Date: 09 May 2019

Registration Date:

09 May 2019

Year of

Manufacture:

2018

Vehicle Type:

Public Transport Taxi (Motor Car)

Vehicle Scheme:

Taxi (Company)

Vehicle

Attachment 1:

Air-Con (Taxi)

Vehicle

Attachment 2:

Vehicle

Attachment 3:

Vehicle Make:

HYUNDAI

Vehicle Model:

AE IONIQ HEV 1.6 DCT

Primary Colour:

Silver

Secondary Colour:

Passenger

Capacity:

Chassis No.:

KMHC851CVKU129685

Engine No.:

G4LEJU156318

Motor No.:

**Engine Capacity** 

PM04JB5333DJ

/Power Rating:

1580 cc / 32.0 kW

Maximum Power

Output:

103.6 kW (138 bhp)