

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

29-Oct-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8811 T

1 pc	Tailgate	\$	2,480.40
1 pc	Emblem "Hyundai"	\$	28.00
1 pc	Emblem "Hybrid"	\$	24.30
1 pc	Emblem "Ioniq"	\$	31.30
2 pcs	Rear n/s & o/s tail lamps	\$	725.20
1 pc	Rear bumper	\$	459.40
1 pc	Rear bumper reinforcement	\$	294.80
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket	\$	20.00
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00
2 pcs	Rear bumper n/s & o/s stay	\$	276.20
2 pcs	Rear bumper n/s & o/s side bracket	\$	66.20
1 pc	Rear bumper lower moulding centre	\$	216.50
1 pc	Rear bumper lower cover	\$	47.50
1 pc	Rear bumper cap hook	\$	9.10
2 pcs	Rear bumper n/s & o/s reflector	\$	63.80
		\$	4,757.70
		Less 20%	\$ 951.54
			\$ 3,806.16

S/N

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00
1 pc	Rear number plate with casing	\$	50.00
1 set	Tailgate stickers	\$	100.00
Sundry		\$	50.00
To check wiring		\$	50.00
To dismantle/refit rear tailgate window glass onto new tailgate		\$	120.00
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc		\$	850.00
To putty and spray painting on rear bumper, end panel, rear bumper lower cover (Black), tailgate		\$	800.00
To apply rustproofing on the repaired and replaced panels.		\$	120.00
		\$	6,574.16

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A = SHB 8811T
B = SFH 6522H




Jalan Kaya

Describe Circumstances of the Accident

Please refer attached

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Pranab Kumar
29/10/2021 12:35 pm

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel

Describe Circumstance of the Accident.

ON 29/10/2021 @ 10:55HRS, I WAS DRIVING MY TAXI – **SHB8811T**, TRAVELLING ALONG JLN KAYU INTO SENGKANG WEST WAY.


I WAS SLOW DOWN AND COMPLETE STOPPED AT SLIP ROAD FOR GIVING WAY TO ONCOMING VEHICLE FROM THE MAIN ROAD. SUDDENTLY, VEHICLE B (SFH6522H- MERCEDES) WHICH WAS BEHIND MY VEHICLE UNABLE STOP IN TIME AND COLIDED ONTO MY REAR PORTION OF MY VEHICLE.


DUE TO THE IMPACT, MY TAXI WAS DAMAGE ON THE REAR PORTION & VEHICLE B WAS DAMAGED ON THE FRONT PORTION.

NO PASSENGER ONBOARD BOTH VEHICLES.

VIDEO CAPTURED

DAMAGES FOUND ON VEHICLE A & VEHICLE B





Driver's Signature
Friday, October 29, 2021 @ 12:25:26 PM

(attended by)

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport /Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHB8811T
 Previous Vehicle No.: -
 Effective Date of Ownership: 09 May 2019
 Original Regn Date: 09 May 2019
 Registration Date: 09 May 2019
 Year of Manufacture: 2018
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: AE IONIQ HEV 1.6 DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: KMHC851CVKU129685
 Engine No.: G4LEJU156318
 Motor No.: PM04JB5333DJ
 Engine Capacity /Power Rating: 1580 cc / 32.0 kW
 Maximum Power Output: 103.6 kW (138 bhp)


INSURER ENQUIRY

Find
insurer

Vehicle reg. no.

SFH6522H

Date of Accident

29/10/2021 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **AIG Asia Pacific Insurance Pte....**Period of Insurance **01/07/2021 - 30/06/2022**Requested By **NG BOON KAI (PREMIER AUTO...**Requested Date **29/10/2021 13:03**

Payment details

Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**