

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21011124/Aqf3e2	
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND PRE 048623		Date:	07/12/2021	
				Code:	SMO	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKP 8398K	Veh. Inspected	d	SLT 1386H	
	Policy No.	D21MTPV01006165	Coverage (\$)		0.00	
	Claim No.	CMTD2103185/THE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		01/11/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN SCIROCCO	c.c		1984	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	WVWZZZ13ZAV410489	Colour		BLUE	
	Odometer	259321 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	235/35 R19	MICHELIN		6 mm	
	L/H Front Tyre	235/35 R19	MICHELIN		6 mm	
	R/H Rear Tyre	235/35 R19	MICHELIN		6 mm	
	L/H Rear Tyre	235/35 R19	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AI UNDERCARRIAGE.			N AND		
5.	General Information					
	Accident Date	25/10/2021	Inspect Date /	Time	01/11/2021 (01:52 PM)	
	Survey held at	RICO 60 AUTO SERVICES PTE	LTD			
	8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$18,000-\$23,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 15 Working Days					
Щ	1					

Report Ref No. CS3/SMO21011124/Aqf3e2

Inspected By

ADRIAN LING WAI PING

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.