



# Service Request Details

Claim

S1M03L3N

Reference

CS3/ASM21011134/y3 

Loss Date

29 October 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

31 Oct 2021 9:26:33 AM

Request Date

1 November 2021

Due Date

9 November 2021

Services

Pending verification - Direct Settlement

## Actions

---

Next Step

Agree to perform service

[Decline Work](#)

## Vehicle Information

---

Incident Vehicle Registration #

SMT5897L

Make

TPVD

Model

TBC

## Service Address

---

'''

## Primary Contact/Insured

---

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

## Claim Handler

---

OH Vale

vale.oh@axa.com.sg

## Additional Instructions

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

New Message

TYPE



SENT

1/11/21 3:49 PM



BODY

Dear Vale, Thank you for the assignment. Repairer...

