


ASSIGNMENT

From: Deloit
 Estimated Cost: _____
 To inspect Vehicle Not: OR / TP / WS / PR / REP / OD / RES / EYA / INV / MV
 at Workshop m/s: _____
 Insured: _____
 Policy No. _____
 Claims No. 6192058360SG
 Sum Insured: _____ Excess: 600
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remarks: The veh had commenced its
 repair at the time of inspection.



Rel. or Market Value: _____
 IDAO Accident Report: _____ Consistent? : Yes or No
 DIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repair: 3 days Res: Yes or No
 Cum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKP 996L Yr Regn: 21/5/19
 Type: Car / M. Cycle / Bus / Van / Lorry / Taxi / Private Motor /
 Truck / Trailer or
 Make: KIA Cerato C.B. 1591
 Colour: Red A/O: Insured / Std / NI / N
 Sp. Reading: 48635 TIR: Insured / Std / NI / N
 Eng/No: _____
 On/O: KNAF 5416 MK 5: 027626
 Gen. Cond: Good / Fair / Poor / Ruined
 Steering: Worder / Jammed / Locked / Burnt or
 Broken: Worder / Jammed / Locked / Burnt or
 Mod: NII / 3/Rim / STD A/Rim or
 Tyre Size: P1 225/45ZR17
 RI: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho
 Front: _____ Rear: _____
 R/Wal: 4 mm R/Wal: 4 mm
 L/Wal: 4 mm L/Wal: 4 mm
 D.O.A. 3/10/21 Cycle & Carriage
 Survey held at: _____
 Des. of Damages: Front LH / Frt / Rear / O/S / H/S / U/C / Roof/Top or
 The U/C / CHASSIS frame / Body structure affected due to collision

Date / Time: _____ Action / Instruction: _____

MV-70K

02/11/21@3.10pm revert to AIG via Merimen.
 02/11/21@6.49pm Kok Chong informed C/A via Merimen.
 03/11/21@9.43am Informed Coco C/A & ex.\$600 by email.
 18/11/21@3.32pm confirmed with Ms Loi final fig \$7187.60, 3 days. (Red \$2485.40, 26%)

Time/Date, File, Revise: ☐ Prel. Report
☐ Final Report

Days of Repair: 3
 Resurvey No. or Trips: 2

Survey Fee	
Transportation	
Other	
Total	

Add Fee: ☐ Site Insp (\$ _____)
☐ Interview (\$ _____)
☐ Tech. Insp (\$ _____)
☐ Vehicle (\$ _____)

Approved: MER-OD
 Amount: 7187.60



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIU JIALIANG ERIC	Cust No/Name	/LIU JIALIANG ERIC
BLK 309 JURONG EAST STREET 32	Reg No/Reg Date	SKP996L / 21/05/201
#08-278	Date In/Mileage	/ 0
SINGAPORE 600309	Chassis No	KNAF5416MK5027626
Contact No Mobile: 97510251	Engine No	G4FGJH716118
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	01/11/2021/ 13:47	BLC	442 / Cocolu	41918

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 1 RENEW FRT BUMPER, REPAIR FRT FENDER LH 499 X 1				499 800.00
E PNT98000 1 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH 350 X 1				350 700.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY Sundry				20.00
M COVER-FR BUMPER / BR	1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER / BR	1.00	485.00	00.00	485.00
M COVER-FR BUMPER FOG LAMP, LH / BR	1.00	15.00	00.00	15.00
M GRILLE ASSY-RADIATOR ?	1.00	328.00	00.00	328.00
M LAMP ASSY-FRONT FOG, LH ?	1.00	303.00	00.00	303.00
M MOULDING-FRONT BUMPER, LH / BR	1.00	216.00	00.00	216.00
M LAMP ASSY-SIDE REPEATER, LH / CUT	1.00	143.00	00.00	143.00
M ABSORBER-FRONT BUMPER ENERGY ?	1.00	84.00	00.00	84.00
M AIR DUCT-FR BUMPER, LH ?	1.00	14.00	00.00	14.00
M ULTRASONIC SENSOR ASSY-P.A.S ?	1.00	163.00	00.00	163.00
M BRACKET-FR BUMPER UPR SIDE MTG ?	1.00	22.00	00.00	22.00
M ORNAMENT-KIA NO.115 / MK	1.00	32.00	00.00	32.00
M LAMP ASSY-HEAD, LH / CUT	1.00	2210.00	00.00	2210.00

Steve (LKK)
2/11/21, 9-39am

00-11 AL
EXP 11-?
PIP
My BUL by
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

7% GST on	Nett	6,318.00
		442.26
Total Payable		6,760.26

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/11/2021 15:45 (SGT)
Date of Accident	31/10/2021 16:20 (SGT)
Exact Location of Accident	1 HarbourFront Walk, Singapore 098585
Additional Location Information	VIVOCITY CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP996L
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIU JIALIANG, ERIC
NRIC No	SXXXX686J
Email Address	ERICLIU88@GMAIL.COM
Mobile Phone No	(Phone) +65-97510251
Alternative Phone No	+65-97510251

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900091727-01
Cover Note Number	-

DRIVER

Name of Driver	LIU JIALIANG, ERIC
NRIC No	SXXXX686J

Date Of Birth	12/01/1988
Occupation	Indoor
Date Of Driving Pass	22/01/2008
Driving experience	13 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97510251
Alt. Phone Number	+65-97510251
Email Address	ERICLIU88@GMAIL.COM
Address	BLK 309 JURONG EAST STREET 32 #08-278
Address complement	.
Postcode	600309
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	.
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	.
Insurance Company of Other Vehicle Owned by Driver	.

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	CARPARK
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	PAMELA
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT
COLLISION-HEAD TO SIDE

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA3854K
Vehicle Manufacturer	Nissan
Vehicle Model	Note
Vehicle Variant	-
Vehicle Colour	Blue

Vehicle Category	Private car
Name of Driver	MS LEE
Contact Number	(Phone) +65-97319037
Address	-
Address complement	-
Postcode	-
Insurance Company Name	HL Assurance Pte Ltd
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


3/10/2021 13:11
Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A - SP9946L
B - SLA3854K

Describe Circumstances of the Accident


Accident occur in the basement 2 carpark in VivoCity at 1620 on 31/10/2021.

I was turning out toward a one way lane, checked my left before making my turn towards the right. My vehicle was barely moving or at a extremely slow speed of approx 5km/h or lower during the turn. As I was ~~turning~~ turning right, I turn my focus of attention to the right side as I have checked my left before turning. As I beginning turning a car suddenly rolleded into mine out of nowhere. I believe she (87345274J) was driving faster than expected in the carpark and she mention she was in a rush/hurry to pick up her dad for dinner and she was already late.

During the exchanging of information she kept wanting to deny the agreement and leave and mention she will settle later on as she is in a rush.


Declaration

We declare the foregoing particulars are true in every respect.


1/30/2021

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIU JIALIANG ERIC
Period of Insurance : 21 May 2021 To 20 May 2022
Engine No. : G4FGJH716118
Chassis No. : KNAF5416MK5027626

Vehicle No. : SKP996L
Policy No. : 1900091727-01
Endorsement No. :
Issued Date : 17 Apr 2021

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PAF : Yes

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Mileage Condition : Unlimited Mileage

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIU JIALIANG ERIC - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1 Cycle & Camage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2 Cycle & Camage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3 Cycle & Camage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4 Cycle & Camage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622226

C&CKICP2 - WILLAU

239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

AIGSGMOBILEAPP

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #09-16 AIG Building S079120 | T: +65 6419 3000 | www.aig.sg