

ASS. REC. BY

Steve

CS/A/G/2101166/EVF3

ASSIGNMENT

From:

Date:

Veh No:

SKF 9138R

Yr Regn:

26/6/18

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Q/T/P/W/S/T/P/R/S/O/D/R/S/E/V/A/I/N/V/M/V

Truck / Trailer or

To Inspect Vehicle No:

Make: KIA Sorento

CB 2199

at Workshop m/s

Colour: Grey

A/O: Insured / Stolen / N

of

Sp. Reading 80700

T/Radio: Insured / Stolen / N

Insured:

Eng/No:

Policy No. 1800072477-03

O/No:

KNAPH81BMJ5465579

Claims No. 3256621593SG

Gen. Condi Good / Fair / Poor / Bupl

Sum Insured:

Excess:

0

(Client's Record)

Make of Veh:

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

235/55R19

R1

11

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /


TOYO / YOKO or

Falken

(Policy Condition)

Remarks: The veh had commenced its

repair at the time of inspection.



Rel. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

SIA / PR Seen:

Consistent? Yes or No

Est. Repair:

days

Res.:

Yes or No

Cum Sum:

%

3 Vol.:

Yes or No

QA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Front

5

mm

Rear

5

mm

R/Sel:

5

mm

U/Sel:

5

mm

D.O.A.

30/10/21

O.O.L.

2/11/21

Survey held at

Cycle & Carriage

Des. of Damages

FR

Rear

O/S

H/S

UIC

Roof/Top or

The U/S or chassis frame / Body structure affected due to collision

Date / Time Action / Instruction

MV-102K

7/12/21 Final fig \$7166.40 confirmed by email (Red 6366.80, 47%)

Meeting, File Review:



Prel. Report



Final Report

Meeting, File Review:

8/12/21-typist

Merimen

\$7166.40

Days Of Repair:

4

Resurvey No. of Trips:

1

Survey Fee:

Transportation

S. & P.S.

Fuels

Others

TOTAL

Add Fee:



Site Insp

(\$



Interview

(\$



Tech. Invo

(\$



Veh. Detail

(\$



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Khng Yong Meng Edmund
	Reg No/Reg Date	SKF9138R / 26/06/201
	Date In/Mileage	/ 80700
	Chassis No	KNAPH81BMJ5465570
	Engine No	D4HBJH373831
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	02/11/2021/ 08:44	TLE	261 / Edwin Caina	41925			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FR BUMPER , BONNET & FR SUPPORT PNL					400			800
REPAIR LHF FENDER								
E PNT98000								1050.00
RESPRAY FR BUMPER , BONNET & LHF FENDER					350			700
E PNT88000								100.00
REMOVE & REFIT AC COND & RADIATOR								?
M SUNDRY								80.00
TOP UP AC GAS								?
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
SUPPLY FR NUMBER PLATE WITH CASING								
E PNT88000								80.00
REMOVE & REFIT FR PARKING ASSIST SENSOR								
M SUNDRY								60.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								20.00
Sundries								
M SUNDRY								?
RE-WRAPPING ACCIDENT PORTION AREAS								2500.00
M PANEL ASSY-HOOD					1.00	1654.00	20.00	1323.20
M HINGE ASSY-HOOD,LH					1.00	87.00	20.00	69.60
M HINGE ASSY-HOOD,RH					1.00	87.00	20.00	69.60
M CLIP-HOOD INSULATING PAD MTG					13.00	1.00	20.00	10.40
M STRIP ASSY FR-HOOD					1.00	27.00	20.00	21.60
M LATCH ASSY-HOOD					1.00	104.00	20.00	83.20
M COVER ASSY-RADIATOR GRILLE UPR					1.00	186.00	20.00	148.80
M GRILLE ASSY-RADIATOR					1.00	673.00	20.00	538.40
M COVER-FR BUMPER UPR					1.00	561.00	20.00	448.80
M MOULDING-FRT BPR LICENSE PLATE					1.00	20.00	20.00	16.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Khng Yong Meng Edmund
	Reg No/Reg Date	SKF9138R / 26/06/201
	Date In/Mileage	/ 80700
	Chassis No	KNAPH81BMJ5465570
	Engine No	D4HBJH373831
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	02/11/2021/ 08:44	TLE	261 / Edwin Caina	41925		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	MOULDING-FRONT BUMPER LWR,LH			1.00	89.00	20.00	71.20
M	MOULDING-FRONT BUMPER LWR,RH			1.00	89.00	20.00	71.20
M	LIP-FRONT BUMPER			1.00	56.00	20.00	44.80
M	SKID PLATE-FR BUMPER			1.00	111.00	20.00	88.80
M	GRILLE-FRONT BUMPER			1.00	191.00	20.00	152.80
M	ABSORBER-FRONT BUMPER ENERGY			1.00	117.00	20.00	93.60
M	STIFFENER ASSY-FR BUMPER LWR			1.00	117.00	20.00	93.60
M	BRACKET-FR BUMPER SIDE,LH			1.00	17.00	20.00	13.60
M	BRACKET-FR BUMPER SIDE,RH			1.00	17.00	20.00	13.60
M	ULTRASONIC SENSOR-S.P.A.S			4.00	187.00	20.00	598.40
M	LAMP ASSY-HEAD,LH			1.00	2743.00	20.00	2194.40
M	BEAM COMPLETE-FR BUMPER			1.00	551.00	20.00	440.80
M	CARRIER ASSY-FRONT END MODULE			1.00	760.00	20.00	608.00

SURVEYOR NAME: Steve (LKK) 2/11/21, 9.39amSURVEYOR SIGNATURE: 00- N1 ALDATE: Excess - ?REMARKS: P/P
By Bel sy
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

* To resurvey before/after spray painting

Confirm & accepted by:

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

	Nett	13,304.40
7% GST on	13304.40	931.31
Total Payable		14,235.71

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/11/2021 11:33 (SGT)
Date of Accident	30/10/2021 15:50 (SGT)
Exact Location of Accident	68 Kaki Bukit Ave 6, Singapore 417883
Additional Location Information	68 KAKI BUKIT AVE 6,ARK@KB,EXIT GANTRY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF9138R
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KHNG YONG MENG EDMUND
NRIC No	SXXXX866Z
Email Address	EDKHNG@GMAIL.COM
Mobile Phone No	(Phone) +65-90302093
Alternative Phone No	+65-90302093

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Sorento
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2199

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800072477-03
Cover Note Number	-

DRIVER

Name of Driver	KHNG YONG MENG EDMUND
NRIC No	SXXXX866Z

Date Of Birth	31/10/1975
Occupation	Indoor
Date Of Driving Pass	15/04/1998
Driving experience	23 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90302093
Alt. Phone Number	+65-90302093
Email Address	EDKHNG@GMAIL.COM
Address	7 SEMBAWANG CRESCENT #11-13
Address complement	-
Postcode	757096
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT
COLLISION-THIRD PARTY REVERSED & HIT ONTO INSURED (FRONT)

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE8551Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Gray
Vehicle Category	Goods vehicle
Name of Driver	OH HIAN KEE
Contact Number	-
Address	-

Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time
12/11/2021

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 30/10/2021, I went to Park@KB to do some maintenance to my car (SRF915PR). After the work was completed, I left the workshop and was about to exit the building.


I stopped more than 1.5 metres behind a grey lorry (GRE8551G) at the exit gantry and was waiting for my turn to exit. I saw that the lorry was not raised for the lorry in front and the next thing I knew was that the lorry reversed in a very fast speed and bang onto the right left side of my front bonnet, the hood and


part of the car. I ~~heard~~ ^{heard} the horn just before he ~~hit~~ ^{hit} my car. There were multiple witnesses as there were many workshops around.


After the driver hit my car, he came down to inspect the damages. I did the same and we exchange particulars. He drove off immediately after the exchange.

Declaration

We declare the foregoing particulars are true in every respect.

 10/10/21
Policyholder's Signature / Date & Time

 11/11/21
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KHNG YONG MENG EDMUND
Period of Insurance : 26 Jun 2021 To 25 Jun 2022
Engine No. : D4HBH373831
Chassis No. : KNAPH81BMJ5465570

Vehicle No. : SKF9138R
Policy No. : 1800072477-03
Endorsement No. :
Issued Date : 28 May 2021

ABOUT THE COVER

Make/Model : KIA SORENTO 2.2 A DIESEL
Engine Capacity/Tonnage : 2,199.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Mileage Condition : Unlimited Mileage

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

KHNG YONG MENG EDMUND - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1 Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
- 2 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
- 3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
- 4 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500709926

CYCLE & CARRIAGE - CINDY

239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSPCSI