



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 30.10.2021
Emailed : 04.12.2021, 12.40pm
Date Survey : 02.11.2021

VEHICLE NO : SKF 9138 R
MODEL : KIA SORENTO 2.2 A D SX
WIP : 41925

Material	:	\$	<u>5,326.40</u>
Labour	:	\$	<u>1,840.00</u>
Sub-Total	:	\$	<u>7,166.40</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>7,166.40</u>
GST 7%	:	\$	<u>501.65</u>
Grand Total	:	\$	<u>7,668.05</u>
Finalise By/Date	:	<u>LOI / 04/12/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 02/11/2021	Cust No/Name	/Khng Yong Meng Edmund
	Reg No/Reg Date	SKF9138R / 26/06/2018
	Date In/Mileage	02/11/2021/ 80700
	Chassis/Package	KNAPH81BMJ546557C /#
	Engine No	D4HBJH373831
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	04/12/2021/ 12:30	BLE	260 / AiTing	41925			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800.00
REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 800.00
E PNT98000								700.00
RESPRAY ON FRONT BUMPER, BONNET, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 700.00
A 54900099								30.00
CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901								120.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								✓ 120.00
E PNT88000								80.00
REMOVE & REINSTALL FRONT PARKING ASSIST SENSOR TO FACILITATE REPAIR								✓ 80.00
M SUNDRY								40.00
SUPPLY BODY PANEL SEALANT								✓ 40.00
M SUNDRY								20.00
SUNDRIES								✓ 20.00
S SPECIALISTJOB								50.00
SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								✓ 50.00
X	PANEL ASSY-HOOD				1.00	✓ 1654.00	20.00	1323.20
X	CLIP-HOOD INSULATING PAD MTG				13.00	✓ 1.00	20.00	10.40
X	STRIP ASSY FR-HOOD				1.00	✓ 27.00	20.00	21.60
X	COVER ASSY-RADIATOR GRILLE UPR				1.00	✓ 186.00	20.00	148.80
X	GRILLE ASSY-RADIATOR				1.00	✓ 673.00	20.00	538.40
X	COVER-FR BUMPER UPR				1.00	✓ 561.00	20.00	448.80
X	MOULDING-FRT BPR LICENSE PLATE				1.00	✓ 20.00	20.00	16.00
X	GRILLE-FRONT BUMPER				1.00	✓ 191.00	20.00	152.80
X	ABSORBER-FRONT BUMPER ENERGY				1.00	✓ 117.00	20.00	93.60
X	ULTRASONIC SENSOR ASSY-BWS				1.00	✓ 187.00	20.00	149.60
X	LAMP ASSY-HEAD,LH				1.00	✓ 2743.00	20.00	2194.40
X	WIRING HARNESS-F.P.A.S				1.00	257.00	20.00	205.60
X	DAM-AIR				1.00	29.00	20.00	23.20
Z TEXT								
AIG OD CLAIM, UIL CLAIM GBE8551Z								

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 02/11/2021	Cust No/Name	/Khng Yong Meng Edmund
	Reg No/Reg Date	SKF9138R / 26/06/2018
	Date In/Mileage	02/11/2021/ 80700
	Chassis/Package	KNAPH81BMJ546557C /#
	Engine No	D4HBJH373831
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	04/12/2021/ 12:30	BLE	260 / AiTing	41925			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
DOA: 30.10.21 SURVEYOR STEVE LKK 02.11.21 POLICY NO : 1800072477-03 REPAIR 04 DAYS								
Pro Forma								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	5,326.40	Nett	7,166.40
Labour	1,730.00	7% GST on	501.65
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	7,668.05
Diagnostics Job	0.00		
Sundry/Others	60.00		
Total(w/o GST)	7,166.40		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SKF 9138 R

<u>Materials</u>		<u>Cost (\$)</u>
1	Wiring harness - F.P.A.S	257.00 / BR
2	Dam-Air	29.00 / BR
Total		286.00
Less 20% discount		57.20
Total after discount		228.80
7% GST		16.02
Grand total		<u>244.82</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SKF9138RWIP: 41925

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	GRILLE - FRONT BUMPERS	② SUPP		/ RR	
2	ABSORBER	② SUPP		/ RR	
3	SENSOR	② SUPP		/ RR	Steve 11/11/21
4	LAMP ASSY - HEAD, LH -	② SUPP		/ RR	
5	WIRING HARNESS F.P.A.S	? / SUPP		/ TN	91845 CSO20
6	AIR GUARD LH	? / SUPP		/ CRU	
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
<u>11/11/21</u>	<u>Steve</u>
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF MOUNT TO CELLETTE BENCH	
REMOVE AND INSTALL ENGINE	
REMOVE AND INSTALL DASHBAORD	
REMOVE & INSTALL FUEL TANK	
PHOTO UNDERCARRIAGE PARTS	

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETTE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS




MODEL: SORENTOSURVEYOR: STEVE



Fault Code Searching

Rescan

Save



17/17

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESP	No Current DTC	Good
EPB	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0258

VCI Ver.

02.62

ECU Ver.

M-E-K-01-00-0198

OS Ver.

Android 10