



Exceptional Journeys

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 30.10.2021
 Emailed : 15.11.2021, 5.15pm
 Date Survey : 02.11.2021

VEHICLE NO : SMU 1147 P
 MODEL : MIT ATTRAGE 1.2
 WIP : 17057

Material	:	\$	<u>871.64</u>
Labour	:	\$	<u>2,155.00</u>
Sub-Total	:	\$	<u>3,026.64</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>2,426.64</u>
GST 7%	:	\$	<u>169.86</u>
Grand Total	:	\$	<u>2,596.50</u>
Finalise By/Date	:	<u>LOI / 15/11/2021</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

TP claim _____

Claim GIA / LTA fee _____

Claim Loss of Use / Rental

Claim Medical Fee / Others _____

Third Party Report - _____



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 02/11/2021	Cust No/Name	KCV05222/Mr Nor Hashim Bin Mohamad Isa
	Reg No/Reg Date	SMU1147P / 29/07/2020
	Date In/Mileage	02/11/2021/ 15820
	Chassis/Package	MMBSTA13AKH00334E /#(F)
	Engine No	3A92UJB1536
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	12/11/2021/ 14:57	BLE	260 / AiTing	17057

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR LH REAR FENDER, REAR BUMPER BODY KIT, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 755.00
E PNT98000 RESPRAY ON REAR BUMPER, REAR BUMPER BODY KIT, & LH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1050.00
E PNT88000 REMOVE & REINSTALL REAR FLOOR BOARD, TRIMS & CARPETS TO FACILITATE REPAIR				? 120.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE				✓ 120.00
E PNT88000 REMOVE & REINSTSALL REVERSE SENSOR TO FACILITATE REPAIR				✓ 60.00
M SUNDRY SUNDRIES				✓ 20.00
X EXC EXCESS				-600.00
X LAMP ASSY, COMB, RR LH	1.00	✓ 337.00	23.00	259.49
X FACE, RR BUMPER	1.00	✓ 751.00	23.00	578.27
X BRACKET, RR BUMPER, LH	1.00	✓ 28.00	23.00	21.56
X CLIP, FR BUMPER	(1) 4.00	✓ 4.00	23.00	12.32
Z TEXT AIG OD CLAIM DOA : 30.10.21 SURVEYOR STEVE LKK 02.11.21 POLICY NO : 2070110605 REPAIR 04 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	871.64		Nett	2,426.64
Labour	2,135.00	7% GST on	2426.64	169.86
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	2,596.50
Diagnostics Job	0.00			
Sundry/Others	-580.00			
Total (w/o GST)	2,426.64			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMU 1147 P**

	<u>Materials</u>	<u>Cost (\$)</u>
1	Clips (x3)	12.00 / <i>rec</i>
	Total	----- 12.00
	Less 23% discount	2.76
	Total after discount	9.24
	7% GST	0.65
	Grand total	----- \$ 9.89

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

All DTCS

2021.11.06

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	A13A 2019MY

Page No: 020411177P

Refer to user MTR's box with to Base all the sou

All DTCs

2021.11.06

Job Done
 by B.C. Tech. Condition
 at Tech. drive. Check all
 in Condition

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCs	
AT/CVT/A-MTTC-SST	KOSOSS_99880010		No DTCs	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCs	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCs	
SRS-AIR BAG	KOSOSS_99880010		No DTCs	
Air Conditioner	KOSOSS_99880010		No DTCs	
ETACS	KOSOSS_99880010		No DTCs	
Meter	KOSOSS_99880010		No DTCs	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCs	