

ASS. REC. BY: Steve

CS/EQ/21011219/Eqf3

ASSIGNMENT

From: Dolo
 Estimated Cost: INSURANCE/REP/IVA/INV/MV
 To inspect Vehicle No: 1591
 at Workshop no: 25405
 Insured: KNAF 3416 M: 5062881
 Policy No: Good / Fair / Poor / Bump
 Claims No: Good / Fair / Poor / Bump
 Sum Insured: 205/55R16
 (Client's Record)
 Make of Veh: TOYO / YOKO or

Veh No: SMU18222 Yt Regd: 30/7/20
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Tractor / Prime Mover
 Truck / Trailer or
 Make: KIA Cerato
 Colour: Grey A/O: Insured / Std / NI / N
 Sp. Reading: 25405 TIR: Insured / Std / NI / N
 Eng/No: KNAF 3416 M: 5062881
 On/No: Good / Fair / Poor / Bump
 Gen. Cond: Good / Fair / Poor / Bump
 Steering: Good / Fair / Poor / Bump
 Brakes: Good / Fair / Poor / Bump
 Mod: Good / Fair / Poor / Bump
 Tyre Size: 205/55R16
 RI: Good / Fair / Poor / Bump
 GS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSV / PIR / SUMI /
 TOYO / YOKO or Kumho
 Front: 5 mm 5 mm
 R/Rail: 5 mm 5 mm
 U/Rail: 5 mm 5 mm
 D.O.A. 2/11/21 Cycle & Carriage
 Survey held at 19/11/21
 Des. of Damages: Front / Rear / AIS / NIS / DTC / Rollover or
 The V/O / Chassis / Frame / Body Structure affected due to collision

(Policy Condition)
 Remarks: The veh had commenced its
 repair at the time of inspection.
 Del. or Market Value: Consistent? : Yes or No
 IDAC Accident Report: Consistent? : Yes or No
 SIA / PR Sacc: Consistent? : Yes or No
 Est. Repair: days Rep: Yes or No
 Sum Sum: % 3 Vol: Yes or No
 QA / REV / REP. / 24 HRS
 Date: Person Contacted: Vehicle: IN / OUT

Date / Time: Action / Instruction
MV-80K
confirm the finalize \$2150 (P/P, before GST). 3 repair days.
red: 5161; 70%
3

me/Time, File, Receipt: 1 2
1 2
 Add Fee: 1 2 3 4
 Days of Repair: 3
 Resurvey No. or Trip: 1
 Survey Fee: 1 2 3 4
 Transportation: 1 2 3 4
 S & S: 1 2 3 4
 Fee: 1 2 3 4
 Other: 1 2 3 4
 Total: 1 2 3 4