

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC21011223/R1vce2		
189556			Date:	07-12-2021 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLD 7604Z	Veh. Ir	nspected	SMB 69M	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1149126-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	02/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ OC500LE	c.c		11967	
	Engine No.	HIDDEN	Year o	f Reg.	2009	
	Chassis No.	WEB63442021000178	Colou	r	MULTI COLOUR	
	Odometer	789030	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	275/70 R22.5	CONTI	NENTAL	8 mm	
	L/H Front Tyre	275/70 R22.5	CONTI	NENTAL	8 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	CONTI	NENTAL	8/8 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	CONTI	NENTAL	8/8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	25/10/2021	Inspec	tion Date	02/11/2021	
	Survey held at	Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD				
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705					
5a.	5a. Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					