

(08/11/13) wef
ASS. REC. BY: *Rasul*

REF: NS/INC21011223/R1vc

2920

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s *SMRT*
of _____

Insured: SLD 7604Z *NTUC*

Policy No.

Claims No. MT/1149126-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

1/12/21 Rasul confirmed LS \$2200 (Red 3180.30, 59%)

Veh No: *SM869M* Yr Regn: *2009 / Jun*
Type: M.Car / M.Cycle / ~~Bus~~ / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *MERCEDES BENZ OC5006* c.c. *11967*

Colour: *MULTI* A/C: Insured / Std / NI / NA

Sp. Reading: *789030* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *WED63447021000178*

Gen. Cond: Good / *Fair* / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: *Nil* / S/Rim / STD A/Rim or

Tyre Size: F: *275/70R22.5*
R: *275/70R22.5*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal. *8* mm R/Bal. *8/8* mm

L/Bal. *8* mm L/Bal. *8/8* mm

D.O.A. *25/10/21* D.O.I. *02/11/21*

Survey held at *SMRT*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: *3*

Resurvey No. of Trip: *1*

Survey Fee:

1)

☐

: Final Report

Date/Time, File Return to?

Transportation:

2) 2/12/21-typist

Add Fee: ☐ : Site Insp (\$

) : *S + RS* SI

☐ : Interview (\$

) : Photos

☐ : Tech. Invs (\$

) : Others

☐ : Weekend (\$

)

Report Format : TP

Lump Sum / L.B. (\$ 2200

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/11/2021

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB69M
Case Reference Number	BUS/10/21/5037
Registration Date	6/30/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Meng Yu
Type of Accident	Side Swipe
Accident Date and Time	10/25/2021 6:12 PM
Accident Reported Date and Time	10/25/2021 7:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB69M-RIGHT FRONT BODY SCRATCHED AND DENTED SLD7604Z (TP) INSURED WITH NTUC
Prepared Date and Time	11/2/2021 10:46 AM
Chassis Number	WEB63442021000178
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$1,112.00	\$0.00
Total Spare Part Cost	\$1,593.34	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,825.34	\$0.00
Temp Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	02/11/2021 10:57 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 738692
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/11/2021

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00	1590
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,112.00	942
Total Spray Painting & Panel Beating	\$1,112.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010330	Body	5029	TRIM, WHEELARCH: FOR MB OC500 LE BUS	1.00	\$124.20	10.00	\$111.78	Replace	Repair
006314	CONSUMABLE		ADHESIVE: DIRECT GLAZING	6.00	\$37.00	0.00	\$222.00	Replace	X
006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	X
			SGLOVEBUS STICKERS	1.00	\$200.00	0.00	\$200.00	Replace	new
010227	BODY RH	5019	PANEL, SKIRT: R4, FOR MB OC500 BUS	1.00	\$1,442.10	10.00	\$1,297.89	Replace	repair
006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	X
Total					\$1,963.30		\$1,991.67		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
Hp 9000068
3 days
43
02/11/21 @ 1515
Resy after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/10/2021 16:38 (SGT)
Date of Accident	25/10/2021 18:12 (SGT)
Exact Location of Accident	Blk 280, Singapore
Additional Location Information	CHOA CHU KANG AVE 3 (AFTER BS:44251, BLK 280)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB69M
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	SMRT BUSES LTD
Company Reg No	1XXXXX292D
Email Address	Auto-Svcs-BARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662672
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	MBOC500
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Bus
Transmission	Auto
CC	11967

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097498MFBP
Cover Note Number	-

DRIVER

Name of Driver	MENG YU
Passport No/FIN	GXXXX410W

Date Of Birth
 Occupation
 Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

27/11/1981
 Outdoor
 15/10/2019
 2 YEARS
 Male
 (Phone) +65-68662672
 -
 Auto-Svcs-BARC@smrt.com.sg
 6 ANG MO KIO STREET 62
 -
 -
 No
 Employee
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Side Swipe
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other vehicle or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
 2
 No
 -
 Yes
 1
 No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

On 25/10/2021 at 1812 hrs, I was driving SMB69M, SVC 975B. There were approximate 10 pax onboard. I was travelling approximate Choa Chu Kang Ave 3 at approximate 20km/hr. After Pax Activity at BS: 44521, I proceed to move off from the bus stop when I saw TP was exiting from the side road making a right turn into Choa Chu Kang Ave 3. As I proceed to slow down to allow TP to make a right turn at the 2nd lane, I saw TP rear end vehicle was on the 1st lane, thus I proceed to travel straight when I saw with my RHS mirror that TP reversed his vehicle along the road and TP right rear body collided onto my right front body. There were no personnel injured due to this accident. I called BOCC regarding this accident. BOCC requested me to exchange particulars with TP before continue my revenue service towards BS: 33041 and report this incident to my Ops Sup at BPITH. TP made an abrupt reverse along the road which resulted in this accident. That is all.

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?
 Reasons for not uploading a video of the accident
 Was there any audio recorded?

No
 Yes
 PENDING DOWNLOAD
 No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
 Vehicle Manufacturer
 Vehicle Model

SLD7604Z
 -
 -

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	NG SIOK LANG
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	NTUC Income Insurance Co-operative Ltd
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

SMB69M

Bus/10/21/5037

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

my

 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/TIN No:



A : SM369M
B : SI.D7604Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

1/11/12 dec



particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time _____



Reporting Centre Person(s)'s Signature:
Name: _____
NRIC/ID No: _____