



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/12/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB69M
Case Reference Number	BUS/10/21/5037
Registration Date	30/6/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Meng Yu
Type of Accident	Side Swipe
Accident Date and Time	25/10/2021 6:12 PM
Accident Reported Date and Time	25/10/2021 7:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112923
Special Instruction to ARC,if any	SMB69M-RIGHT FRONT BODY SCRATCHED AND DENTED SLD7604Z (TP) INSURED WITH NTUC
Prepared Date and Time	2/11/2021 10:46 AM
Chassis Number	WEB63442021000178
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,590.00
Total Spray Cost	\$1,112.00	\$942.00
Total Spare Part Cost	\$1,593.34	\$160.00
Total Other Cost	\$0.00	(\$506.40)
TOTAL COST	\$4,825.34	\$2,185.60
Lump Sum Total	\$0.00	\$2,200.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	Rasul
ARC / Surveyor Sign Off Date	02/11/2021 10:57 AM	02/11/2021 5:01 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/12/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00				\$1,590.00		
Total Labour			\$2,120.00				\$1,590.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$1,112.00				\$942.00		
Total Spray Painting & Panel Beating			\$1,112.00				\$942.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$506.40)		
Total Other Costs			\$0.00				(\$506.40)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SGLOVEBUS STICKERS	1.00	\$200.00	0.00	\$200.00	Replace	Replace
6010227	BODY RH	5019	PANEL,SKIRT:R4,FOR MB OC500 BUS	1.00	\$1,442.10	100.00	\$0.00	Replace	Repair
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	100.00	\$0.00	Replace	Repair
4006314	CONSUMABLE		ADHESIVE:DIRECT GLAZING	0.00	\$37.00	0.00	\$0.00	Replace	Not Given
4006315	CONSUMABLE		ACTIVATOR	0.00	\$80.00	0.00	\$0.00	Replace	Not Given
6010330	Body	5029	TRIM,WHEELARCH:FOR MB OC500 LE BUS	1.00	\$124.20	100.00	\$0.00	Replace	Repair
Total					\$1,963.30		\$200.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									