838H

## ASSIGNMENT

From: Date:	Veh No: 560 3579E Yr Regn: 2070 / DEC
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SGQ 35796	Make: B.M.W SOTLUXULY c.c 1998
at Workshop m/s B.I.S Aus Mobile	Colour But A/C: Insured / Std / NI / NA
of 30,763an amprous crescent	Sp.Reading (2137 T/Radio: Insured / Std / NI / NA
Insured: CT (	Eng/No:
Policy No.	C/No: WBA72A6090WW96727
Claims No.	Gen. Cond: Good (Fair) Poor / Burnt
Sum Insured: Excess:	Steering: prorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: (norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 245/YoRM
(Policy Condition)	R: 22
Remark: The veh had commenced its N/S O/S	<del></del>
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	-V
	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. ( mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 28 10 21 D.O.I. 09/11/2(
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU  Date: Person Contacted:	1
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
REPAIR LIMIT-122K	
te/Time, File Pass to? : Prell. Report	Days Of Repair:
25일 : [1] : 15 : [15 :	
: Final Report	Resurvey No. of Trip:
: Final Report	Resurvey No. of Trip: Survey Fee:
: Final Report	Transportation:
: Final Report	Transportation:  Site Insp (\$ )S+RS,SI
: Final Report ate/Time, File Return to?	Transportation:  Site Insp (\$ )S + RSSI

### MW SERVICE CENTRE

Teban Gardens Crescent Singapore 608927

Automobiles Pte Ltd

Reg. No. 201908617D. GST Reg. No. 201908617D



#### **ESTIMATES**

Estimate No.

: 21998810

Date Estimated

: 02/11/2021

Prepared By

Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -

LKK Auto Consultants hence notify the Repairer of the following:

ACCOUNT -

Chan Tee Seng

• To resurvey before/after spray painting

China Taiping Insurance(S)

To display damaged part(s) during resurvey

Pte Ltd

Parts prices are subject to confirmation

3 Anson Road • Third party survey is on a "Without Prejudice" basis #16-00 Springleaf Tower

No illegal modification(s) is allowed

Singapore 079909

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Md tor Claims Department

REGN. NO. SGQ3579E

CHASSIS NO.

WW96727

RH handle

Acknowledged by Repairer

REGN. DATE MODEL

Signature: Date:

18/12/2020 520

ORIGINAL PRICE

DESCRIPTION

To make good the rear bumper, rear RH fender, rear RH door include removing attachments to facilitate repairs

and knocking out dents caused by the accident

To spray paint rear bumper, rear RH fender, rear RH door and rear

To replace rear RH door handle mechanism include conducting checks on all door sensors and central locking system for proper function

To check electrical wiring systems and lightings include resetting and checking airbags for proper function

Sundries

DESCRIPTION

51 21 9491462 Door handle, prime **repair** 

UNIT PRICE

OTY

96.90

Total Labour:

1.00

NETT 96.90

Rasul
Hp 90010068
5 days
09/11/21@1600
Resurry afterrapair

Total Parts: Total Labour & Parts: 6,122.50 96.90

Deduction for Excess:

5,499.40

Total Repair Costs less Ex GST @7%:

5,499.40 384.96

Grand Total:

5,884.36



## **SINGAPORE ACCIDENT STATEMENT**

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

29/10/2021 14:07 (SGT) 28/10/2021 14:35 (SGT) Jln. Ahmad Ibrahim, Singapore AYE TOWARDS TUAS (OPPOSITE FABER DR) Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SGQ3579E

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No

**Email Address** Mobile Phone No. Alternative Phone No. No

CHAN TEE SENG SXXXX838H

chanteeseng@gmail.com (Phone) +65-96245249 +65-96245249

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to vour vehicle?

Vehicle Category Transmission

CC

**BMW** 520i

Private use

No - Claiming third party Private car

Auto 1998

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number

Direct Asia Insurance (Singapore) Pte Ltd Comprehensive

No

MT/00881826

DRIVER

Name of Driver NRIC No

CHAN TEE SENG SXXXX838H



oate Of Birth Occupation Date Of Driving Pass **Driving** experience Gender Mobile Number Alt. Phone Number **Email Address** Address Address complement Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

١

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

**DETAILS OF POLICE ACTION** 

Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes Yes No

XE1246R

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver Contact Number Address

Address complement

Goods vehicle DINISLAM MD (Phone) +65-81069345

05/08/1965 Indoor 03/12/1988

32 YEARS AND 10 MONTHS

(Phone) +65-96245249

+65-96245249

chanteeseng@gmail.com 31 MOUNT SINAI RISE #18-06

S276953 Yes

No

Collision - Change/cross lane Clear Dry

No

2 No

Yes

No

No

No

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Pease report correctly the details of the addition to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful marepresentation or withholding of meterial facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liab@ly on the part of the insurance
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaxi.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to cofect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to Ine claims
- (ii) investigating the accident and/or my claims.
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as wiell as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the 'Purposes")

- (b) all insurer(s) witho have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect. use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Parsonal Information may/can be disolated by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Time 28

Sketch Plan

Driver's Signature (f driver is not the poticyhokier) / Date

& Tinya

Witnessed by Reporting Centre Personnel.

Sag 1579E

tivet

Describe Circumstances of the Accident

Alons	(Cor A)	
The same of the property of the party of the	clan Ahmad Brahim, of 2	30pm I Vas
Coming of	it of a clip road a	nd filtering
suta ith	e 2nd lone - 14	lone was blocked
THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAM	accident ohead. As I fille	그리고 나이에 뭐 [2007] 이 회사는 문화에 어떻게 있었다면 없었다면 하는데 그리고 그리고 있다.
TELECOR EXPERIENCE INCORRECCIONO INSCINENTALINA CONTRA CARROLLA CONTRA CARROLLA CONTRA CARROLLA CARROL	w a questerney into th	
the truck	a grazing into my right	site near my
back door	I immediately pull to the s	ide, and signated
to the +	ruck to pull heids . We	both pulled up
on the li	ft lane, right up to the	road block where
the road	nicident ahead hoppened. It I	TA that who was
Munging - fly Acci	deal come up to facilitate.	Ac sursasted we
(mycell) mont	and the driend the truck.	ochange contact
Vetoils and	tala photos.	
	12/12 / 10/033	
THE RESIDENCE OF THE PARTY OF T	1895 N. P. S. (17) A. (17) A. (18) A.	
	The state of the s	A CONTROL OF THE STATE OF THE S
	WE WELL TO SECURE A SECURE AS	
AND COLUMN ASSESSMENT AND ASSESSMENT ASSESSM		
	The state of the s	A CONTRACTOR OF THE PROPERTY O
	The second secon	The state of the s
	quant and control of the control of	
and the second s		
The state of the s	THE CONTRACT OF THE CONTRACT O	
	The state of the s	The Middle and and the following constraints and the second secon
	A State of the Sta	
Declaration		
tills declare the threamen early.		78/10/
We declare the foregoing particulars	are the mevery respect,	26/10
6		$\cap$
the	flow	
folloyholder's Signature Date & ime	Oriver's Signature (if driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel
		CONTRACTOR SALES

### > Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	836H
/ehicle No.:	SGQ3579E
Vehicle to be Exported:	No.
ntended Deregistration Date:	10 Nov 2021
Vehicle Make:	BMW
Vehicle Madel:	5201 LUXURY ADAP LED HL
Primary Colour:	Blue
Manufacturing Year:	2020
Engine No.:	11806202B48B20A
Chassis No.:	WBA72AG090WW96727
Maximum Power Output:	137.2 kW (183 bhp)
Open Market Value:	\$54,239,00
Original Registration Date:	18 Dec 2020
First Registration Date:	18 Dec 2020
Transfer Count:	o la
Actual ARF Paid:	\$69,631.00
PARF Eligibility:	
PARF Eligibility Expiry Date:	17 Dec 2030
PARF Rebate Amount:	\$52,223,00
PART REDAIL PARTICULAR.	\$32,22300 Market 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
COE Expiry Date:	17 Dec 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,012.00
COE Rebate Amount:	\$40,970.00
Total Rebate Amount:	\$93,193.00

The information contained herein is correct as at 10 Nov 2021

# BMW 5 Series 520i Luxury

Overview	Financial	Accessories	Similar	Research	Photos	Мар
Price	\$212,	800				
Depreciation	\$20 <b>,05</b> View n	0 /yr nodels with similar d	Reg D epre	ate	14-Oct-2020 (8yrs 11mths	3days COE left)
Mileage	9,000 1	km (8.4k /yr)	Manul	actured 🙆	2020	
Road Tax	\$1,210	/yr	Transı	mission .	Auto	
Dereg Value	\$86,94	2 as of today (chang	je) OMV (	2	<b>\$53,</b> 045	
COE	\$40,69	0	ARF (	j.	\$67,481	
Engine Cap	1,998 ו	cc	Power		135.0 kW (181	bhp)
Curb Weight	1,540	<b>(</b> 0	No. of	Owners ()	1	
Type of Vehic	ile Luxury	Sedan				