PRS Rec. By: GQ | REF: CS3/GAI21011265/Guf3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 111L

at Workshop m/s 1 STOP GARAGE

of

Insured: GBJ 6754S

Policy No.

Claims No. CLMOMVC000004073

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $120k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP111L Yr Regn: 09 Nov 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: AUDI A5 SPORTBACK 2.0 c.c 1984

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 126220 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ8T3BA010239

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/35R19

R: 245/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	05-11-2021

Survey held at W/S 12PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Total Rebate Amount $31,101
	$4000 - $5000, 5 repair days
8/11/2021	Submit PRS.

Date/Time, File Pass to? 1) 8/11 TYPIST

Date/Time, File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format: TP

Lump Sum / UPD: 0

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL