



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21009747/Gvf3e2-1	
			Date: 29/11/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 8317D	Veh. Inspected	SLE 909K
	Policy No.	Z21VC05005908	Coverage (\$)	0.00
	Claim No.	21/21/21/VC05/024964	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	05/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SYLPHY 1.6	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MNTBBAB17Z0027489	Colour	RED
	Odometer	47870 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/09/2021	Inspection Date	29/09/2021
	Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	