


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SGR 68814
 at Workshop m/s Volkswagen
 of 247, Alexandra Rd
 Insured: 111
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 104K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGR 68814 Yr Regn: 2019 / SEP
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volkswagen PASSAT 1.8 c.c. 1798
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp.Reading: 41096 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NVW2223CZKG125075
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/40R19
 R: ~
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 03/11/21 D.O.I. 09/11/21
 Survey held at Volkswagen
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Repair Limit - 49K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I. (\$ _____)

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
GOH
SER SIAN ARDEN
(WU SHIXIAN ARDEN)
3A ONTARIO AVENUE
#02-05
SINGAPORE 576192

Document no.
Document date 05-11-2021
Customer no. 5211000972
Customer GST-ID 198703792K
Dealer 30001
Job order number 2021041988/ 1
Job order date 05-11-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SGR6881G	3G24JZC0	27-09-2019	WVWZZZ3CZKE125075	Passat Comfortline 1.8 TSI 132kW DSG	37,846

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00 ✓	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00 ✓	513.60
3G0853687 2ZZ	Inscription Bright Chrome NAME PLATE - PASSAT	1	pcs.	76.27	#1	76.27	81.61
3G5807417 GRU	Cover Primed REAR BUMPER	1	pcs.	1,725.58	#1	1,725.58	1,846.37
3G0807521B GRU	Spoiler Primed	1	pcs.	296.35	#1	296.35	317.09
N 90346302	Pop-Rivet	10	pcs.	1.23	#1	12.30	13.16
3G0807305T	Bumper REINFORCEMENT	1	pcs.	663.77	#1	663.77	710.23
3G5807863	Attachment Strip BUMPER CTR BRACKET	1	pcs.	63.73	#1	63.73	68.19
3G5807483A	Guide LHR BUMPER BRACKET (UPPER)	1	pcs.	23.92	#1	23.92	25.59
3G5807484A	Guide RHR BUMPER BRACKET (UPPER)	1	pcs.	23.92	#1	23.92	25.59
3G5807375	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	40.88	#1	40.88	43.74
3G5807376	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	40.88	#1	40.88	43.74
3G0998491	1 Set Sensor Brackets	1	pcs.	46.02	#1	46.02	49.24
5Q0919275B GRU	Sensor Primed	2	pcs.	178.98	#1	357.96	383.02
5Q0919133 9B9	Seal Ring Satin Black	2	pcs.	1.32	#1	2.64	2.82
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	81.39	#1	81.39	87.09
D 822150A1	Bonding Agent For Plastic	1	pcs.	65.42	#1	65.42	70.00
3G0853841 2ZZ	Decorative Moulding Brigh BUMPER LOWER CHROM LH	1	pcs.	173.63	#1	173.63	185.78
3G0853842 2ZZ	Decorative Moulding Brigh BUMPER LOWER CHROM RH	1	pcs.	173.63	#1	173.63	185.78
3G0853835 2ZZ	Decorative Moulding Brigh BUMPER LOWER CHROM (CTR)	1	pcs.	226.18	#1	226.18	242.01
1K8943021D	Led Licence Place Light	2	pcs.	100.95	#1	201.90	216.03
3G0945103A	Reflector LHS REFLECTOR INNER	1	pcs.	69.70	#1	69.70	74.58
3G0945105A	Reflector LHS REFLECTOR OUTER	1	pcs.	69.70	#1	69.70	74.58
3G5813315	Lock Carrier REAR END PANEL	1	pcs.	422.98	#1	422.98	452.59
D 007500A2	Zinc Spray	1	pcs.	69.13	#1	69.13	73.97
D 180003M2	2k-Body Adhesive	1	pcs.	445.77	#1	445.77	476.97
D 476KD1M2	Sealant Can Be Sprayed LABOUR	1	pcs.	64.55	#1	64.55	69.07
	SPRAY PAINT	6	pcs.	840.00	#1	5,040.00	5,392.80
	R&R REAR LUGGAGE TRIM	4	pcs.	800.00	#1	3,200.00	3,424.00
		1	pcs.	840.00	#1	840.00	898.80

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
GOH
SER SIAN ARDEN
(WU SHIXIAN ARDEN)
3A ONTARIO AVENUE
#02-05
SINGAPORE 576192

Document no.
Document date 05-11-2021
Customer no. 5211000972
Customer GST-ID 198703792K
Dealer 30001
Job order number 2021041988/ 1
Job order date 05-11-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SGR6881G	3G24JZC0	27-09-2019	WVWZZZ3CZKE125075	Passat Comfortline 1.8 I TSI 132kW DSG	37,846

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	REAR NUMBER PLATE <i>64</i> ✓	1	pcs.	80.00	#1	80.00 ✓	85.60

Quotation valid till 12-11-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	14,598.20	7%	1,075.07	15,358.20	16,433.27
Total	760.00	14,598.20		1,075.07	15,358.20	16,433.27

Customer



---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASU
Hp 90010068
3 days
09/11/21 @ 1045
Resurvey before paint

Autumn
vs
motor
- Out
- Gate view

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 05/11/2021 10:00 (SGT)
Date of Accident 03/11/2021 18:20 (SGT)
Exact Location of Accident Braddell Rd, Singapore
Additional Location Information BRADDELL ROAD (ENTRANCE RAMP ONTO FLYOVER AT BISHAN ROAD -BRADDELL ROAD INTERSECTION)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGR6881G
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner GOH SER SIAN ARDEN (WU SHIXIAN ARDEN)
NRIC No S7432673J
Email Address ARDENGSS@YAHOO.COM.SG
Mobile Phone No (Phone) +65-81988481
Alternative Phone No (Office) +65-98289603

VEHICLE PARTICULARS

Manufacturer Volkswagen
Model Passat
Variant VW PASSAT 1.8 L
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1800

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number SP2000515915
Cover Note Number -

DRIVER

Name of Driver GOH SER SIAN ARDEN (WU SHIXIAN ARDEN)

IC No	S7432673J
Date Of Birth	10/10/1974
Occupation	Indoor
Date Of Driving Pass	12/09/1995
Driving experience	26 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81988481
Alt. Phone Number	(Office) +65-98289603
Email Address	ARDENGSS@YAHOO.COM.SG
Address	3A ONTARIO AVE
Address complement	#02-05
Postcode	576192
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE SKETCH PLAN & ACCIDENT STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM4656X
Vehicle Manufacturer	Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	XIE ZHENYU COSMO
Contact Number	(Phone) +65-81254083
Address	-

Press complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

757700, Singapore

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
Policyholder's Signature / Date &
Time 5 Nov 21, 0830hrs
Sketch Plan

Same as policy holder
Driver's Signature (if driver is not the policyholder) / Date
& Time

[Stamp: RECEIVED REPORTING CENTRE]
Witnessed by Reporting Centre
Personnel

[Grid area for sketch plan]

A
B
↑

A - SGR 688K
B - BLK 4656X

Describe Circumstances of the Accident

I was conveying along Braddell Road, awaiting to enter the slip-ramp (RHS) onto the flyover at Bishan Road - Braddell Road intersection. Traffic flow was heavy, so cars were slowly inching forward. I was travelling slowly (<40km/h) when my rear was knocked into by a car from behind.


My car jolted forward and I came to a halt when I realised I was knocked into.

The 3rd party driver approached me and apologised for knocking into my car's rear end.


He explained he was being pressured by a lorry who was behind him to speed up, and did not pay attention to my car's proximity when he hit me.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time
5 Nov '21, 0830hrs

Same as policy holder
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	673J
Vehicle No.:	SGR6881G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Nov 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT BB 1.8 TFSI AT 3G24JZ
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	CJS308743
Chassis No.:	WWWZZZ3CZKE125075
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$28,711.00
Original Registration Date:	27 Sep 2019
First Registration Date:	27 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$32,196.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2029
PARF Rebate Amount:	\$24,147.00
COE Expiry Date:	26 Sep 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$40,002.00
COE Rebate Amount:	\$30,409.00
Total Rebate Amount:	\$54,556.00










The information contained herein is correct as at 10 Nov 2021

OK

Volkswagen Passat 1.8A TSI

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$107,800		
Depreciation 	\$11,310 /yr View models with similar depre	Reg Date	19-Dec-2019 (8yrs 1mth 8days COE left)
Mileage	38,800 km (20.5k /yr)	Manufactured 	2019
Road Tax 	\$976 /yr	Transmission	Auto
Dereg Value 	\$54,881 as of today (change)	OMV 	\$28,710
COE 	\$37,900	ARF 	\$32,194
Engine Cap	1,798 cc	Power	132.0 kW (177 bhp)
Curb Weight 	1,480 kg	No. of Owners 	1
Type of Vehicle	Luxury Sedan		