

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
GOH
SER SIAN ARDEN
(WU SHIXIAN ARDEN)
3A ONTARIO AVENUE
#02-05
SINGAPORE 576192

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
05-11-2021
5211000972
198703792K
30001
2021041988/ 1
05-11-2021
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SGR6881G	3G24JZC0	27-09-2019	WWWZZZ3CZKE125075	Passat Comfortline 1.8 I TSI 132kW DSG	37,846

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
3G0853687 2ZZ	Inscription Bright Chrome NAME PLATE - PASSAT	1	pcs.	76.27	#1	76.27	81.61
3G5807417 GRU	Cover Primed REAR BUMPER	1	pcs.	1,725.58	#1	1,725.58	1,846.37
3G0807521B GRU	Spoiler Primed	1	pcs.	296.35	#1	296.35	317.09
N 90346302	Pop-Rivet	10	pcs.	1.23	#1	12.30	13.16
3G0807305T	Bumper REINFORCEMENT	1	pcs.	663.77	#1	663.77	710.23
3G5807863	Attachment Strip BUMPER CTR BRACKET	1	pcs.	63.73	#1	63.73	68.19
3G5807483A	Guide LHR BUMPER BRACKET (UPPER)		pcs.	23.92	#1	23.92	25.59
3G5807484A	Guide RHR BUMPER BRACKET (UPPER)		pcs.	23.92	#1	23.92	25.59
3G5807375	Guide Piece LHR BUMPER BRACKET (SIDE)		pcs.	40.88	#1	40.88	43.74
3G5807376	Guide Piece RHR BUMPER BRACKET (SIDE)		pcs.	40.88	#1	40.88	43.74
3G0998491	1 Set Sensor Brackets	1	pcs.	46.02	#1	46.02	49.24
5Q0919275B GRU	Sensor Primed	2	pcs.	178.98	#1	357.96	383.02
5Q0919133 9B9	Seal Ring Satin Black	2	pcs.	1.32	#1	2.64	2.82
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	81.39	#1	81.39	87.09
D 822150A1	Bonding Agent For Plastic	1	pcs.	65.42	#1	65.42	70.00
3G0853841 2ZZ	Decorative Moulding Brigh BUMPER LOWER CHROM LH	1	pcs.	173.63	#1	173.63	185.78
3G0853842 2ZZ	Decorative Moulding Brigh BUMPER LOWER CHROM RH	1	pcs.	173.63	#1	173.63	185.78
3G0853835 2ZZ	Decorative Moulding Brigh BUMPER LOWER CHROM (CTR)	1	pcs.	226.18	#1	226.18	242.01
1K8943021D	Led Licence Place Light	2	pcs.	100.95	#1	201.90	216.03
3G0945103A	Reflector LHS REFLECTOR INNER	1	pcs.	69.70	#1	69.70	74.58
3G0945105A	Reflector LHS REFLECTOR OUTER	1	pcs.	69.70	#1	69.70	74.58
3G5813315	Lock Carrier REAR END PANEL	1	pcs.	422.98	#1	422.98	452.59
D 007500A2	Zinc Spray	1	pcs.	69.13	#1	69.13	73.97
D 180003M2	2k-Body Adhesive	1	pcs.	445.77	#1	445.77	476.97
D 476KD1M2	Sealant Can Be Sprayed LABOUR	1	pcs.	64.55	#1	64.55	69.07
	SPRAY PAINT	6	pcs.	840.00	#1	5,040.00	5,392.80
	R&R REAR LUGGAGE TRIM	4	pcs.	800.00	#1	3,200.00	3,424.00
		1	pcs.	840.00	#1	840.00	898.80

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
GOH
SER SIAN ARDEN
(WU SHIXIAN ARDEN)
3A ONTARIO AVENUE
#02-05
SINGAPORE 576192

Document no.
Document date 05-11-2021
Customer no. 5211000972
Customer GST-ID 198703792K
Dealer 30001
Job order number 2021041988/ 1
Job order date 05-11-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SGR6881G	3G24JZC0	27-09-2019	WVWZZZ3CZKE125075	Passat Comfortline 1.8 TSI 132kW DSG	37,846

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	REAR NUMBER PLATE 64 ✓	1	pcs.	80.00	#1	80.00 ✓	85.60

Quotation valid till 12-11-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	14,598.20	7%	1,075.07	15,358.20	16,433.27
Total	760.00	14,598.20		1,075.07	15,358.20	16,433.27

Customer



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resul
Hp 90010068
3 days
09/11/21@1045
Resurvey before paint