

REC BY: Steve | Ref: CS/LPC21011325/ET43

ASSIGNMENT

07 May 2014

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SBS 6744Y Yr Rog: \_\_\_\_\_  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mercedes-benz Citaro c.c. 7100  
 Colour: Multi-colour A/C: Insured / Std / NI / NA  
 Sp. Reading: 670390 T/Radio: Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C/No: WEB67808323125361  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Knock / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Knock / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / SIRIm / STO A/B/H or \_\_\_\_\_  
 Tyre Size: F: 295/80R22.5  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  

N/S	O/S
XXXX	XXXX

  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3-Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  

Front	Rear
R/Bal. <u>4</u> mm	R/Bal. <u>4</u> mm
L/Bal. <u>4</u> mm	L/Bal. <u>4</u> mm
D.O.A. <u>4/11/21</u>	D.O.I. <u>8/11/21</u>

 \*Survey held at SBS Transit  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/tp or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>NO GIA report</u>
	<b>submit 29704.70, 10Days</b>
	<b>RED:0:0%</b>

Case Time File Pass to?  : Provl. Report  
 1)  : Final Report  
 Date/Time File Return to? \_\_\_\_\_

Days Of Repair: **10**  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$) )  
 : Interview (\$) )  
 : Tech. Inve (\$) )  
 : Wash and ... )

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS: \_\_\_\_\_  
 Flakes: \_\_\_\_\_  
 Glass: \_\_\_\_\_  
 TOTAL: \_\_\_\_\_