

ASSIGNED BY: hcl

CS/ CI 21011331/Gvy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s GBS

of _____

Insured: CB 8521P

Policy No. DMB1SNW00014262100

Claims No. SNM21D206279/C02/THAMYL

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBS 87896 Yr Regn: 23 Sep 2009

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SCANIA KUB 4X2 cc 9290

Colour: Multicolor A/C: Insured / Std / NI / NA

Sp Reading: 890482.6 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YS2K 4X20001-865670

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 225/70R225

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 2/11/21

Survey held at W/S

Des. of Damages: Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 28-11-21

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No fix provided
GIA

Complete estimate give later

12/11/21 Submit \$2835 (Red 184, 6%) (un-confirmed)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 12/11/21-typist

Report Format:

Equip. Serial / Make:

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Misc. (\$)

Survey Fee:

Transportation:

3 + RS \$

Photos

Other:

Total:

Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-17 International Plaza Singapore 079903.

Tel: 90036715 Fax: 62256130 Email: soonbee_vehicle@yahoo.com.sg

GST Registration No: 53076555A

Our Ref No. : SB-19504

Date: 02-Nov-21

AMK Workshop.
Foreman: Li Ming
FAX: 64562752

QUOTATION FOR ACCIDENT REPAIR ON BUS NO:

LKK Auto Consultants hence notify
the Repairer of the following:







- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: SBS8789G

Date:

We are pleased to offer our best proposal to provide our services of labour for repair of above mentioned vehicle at SBS Transit, Ang Mo Kio Workshop.

1)	Vehicle No : Model :	SBS8789G SD												
2)	Total Cost :	<table><tr><td>- Material & Parts Cost</td><td>:</td><td></td></tr><tr><td>- Labour Cost</td><td>:</td><td>\$ 850.00 ✓</td></tr><tr><td>GST (7%) :</td><td></td><td>\$ 59.50</td></tr><tr><td>Total :</td><td></td><td>\$ 909.50</td></tr></table>	- Material & Parts Cost	:		- Labour Cost	:	\$ 850.00 ✓	GST (7%) :		\$ 59.50	Total :		\$ 909.50
- Material & Parts Cost	:													
- Labour Cost	:	\$ 850.00 ✓												
GST (7%) :		\$ 59.50												
Total :		\$ 909.50												
	Work Scopes	<p>Dismantle and replace rear bumper assy Dismantle and replace rear engine access door Repair o/s/r lighting panel Repair n/s/r lighting panel Dismantle and replace n/s/r tail light 3pcs Repair n/s/r dome panel Touch up putty on accident area Respray accident area</p> <div></div> <p>Supply workers for 22 ManHour</p> <p>TERM OF PAYMENT: 30 DAYS UPON DELIVERY OF VEHICLES Vehicle Electric and wiring system not included</p> <p>(B) Materials and Parts: - Supply by SBS Transit</p> <p>(C) Mechanical/Engine Effect - NA</p> <p>2 Days</p>												

Note: Quotation valid for 1 Month only

This is a computer-generated document. No signature will be required.