Sarveyor:	REF: CS1/LA	W21011341/Uty3	Special Instruction;	
From (Person): HENG XIN YI Estimated Cost;	of SEAHONG	NMENT (Office) Date/Time: 08.11.2021	LS: 27,200 Third Parties: Claimant:	
OD/TP Re-inspection / Evalua To Inspect Vehicle No: at Workshop m/s BLUWEL AUT of BLK 1 KAKI BUKIT A	SKQ 6452U OMOTIVE SERVICE P	L Tel:	Surveyor: Workshop:	
Policy No: Sum Insured: Make of Veh: (Client's Record)		Claim No: 19.27068 PI Excess:	-	
Date/Time: Confine Date/Time: 25/11/2021 Submit	med with	ol Fig.	10 / 0/ 0	17
Date/Time Action/Instruction				
Para(1): Parts found no	replaced (To hi	ghlight R or UB, L	R, Etc)	
Para(2): Comments on				
Para(2): Comments on o	onsistency of dam	ages (Parts Not Consist	ent: NC)	
Para(3) : Nett Value				
Salvage Value Nett Value	:	Inspected/ Evaluated by:	Fee Charged: Basic & Add Transport Photos Others Total	Date:
1) Date/TimeF	le Pass to	2) Date/Time		L
3) Date/TimeF	le Pass to	4) Date/Time		
5) Date/TimeF	le Pass to	6) Date/Time	File Return to	