

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC7806K

Date: 08/11/2021

Make : HYUNDAI

Insurance: AIG

Model : IONIQ(G2)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			de \$430.90
10	FRT BUMPER CLIPS			net \$22.00
1	FRT BUMPER SIDE BRACKER RH			? \$28.00
1	FRT BUMPER MOULDING CENTRE UPPER			ant \$368.50
1	HEADLAMP RH			over \$1,993.65
1	DAY LIGHT RH			X \$642.50
1	FRT BUMPER SIDE GRILLE RH			ant \$93.45
1	EMBLEM BLUE - DRIVE RH			X \$26.60
	SUB TOTAL			\$3,605.60
	LESS 20%			\$721.12
	DISCOUNTED TOTAL			\$2,884.48
	FRT FENDER ADVERTISEMENT LOGO RH			X \$100.00 nett
				\$100.00 nett
	Labour Charge			
	PANEL BEATING		350	\$1,050.00
	SPRAY PAINTING CHARGE		250	\$600.00
	CHECK ALL LIGHTING		30	\$60.00
	TOTAL LABOUR			\$1,710.00
	ESTIMATE TOTAL			\$4,694.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 WP 8/11/21 @ 4pm
 p/p Resurvey before paint.
 Tanpin @ Khatow
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is cr. a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 08.11.2021 11:11

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD

Sales Order: 4137895

JC NO: 305493554


IS CITYCAB PTE LTD OMER NO. 7010070 LESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65551188 (O) (P) JUNT CARD NO.	REGN NO.: SHC7806K	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G2)	DATE/TIME IN 08.11.2021 09:15
	YR OF MANU. 06.08.2019	TARGET DATE
	CHASSIS CODE KMHC851CVKU165203	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 07.11.2021

ATURE: 3p 07.11.2021

NO LABOR CODE DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Adgement Slip

Exit Pass

Vehicle No.:

Io.: SHC7806K

YY

SHC7806K

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard