

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / ☐ S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s 1ST AUTOPRO

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$66k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SCE2218P

Yr Regn: 13 Jun/2016

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W. 216D c.c. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 84632 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA2E32090P836757 *

Gen. Cond ☒ Good ☐ Fair / Poor / BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 205/55R17

R: 205/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 09-11-2021

Survey held at W/S 2PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRONT

The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

GIA GIVE LATER

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Filed:

Long Copy/MP/...

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL