

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/196K GS1 Reg. No. 19-900/196-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL		Ref:	CS/AGI21011417/Kvf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		Date:	26/11/2021	
				Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGY 9434H	Veh. Inspected		SKX 560T	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10012383/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		09/11/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MAZDA BIANTE (A)	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	JM6CC1071G0108959	Colour		METALLIC MAROON	
	Odometer	75770 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	NEXEN		9 mm	
	L/H Front Tyre	205/60 R16	NEXEN		9 mm	
	R/H Rear Tyre	205/60 R16	NEXEN		9 mm	
	L/H Rear Tyre	205/60 R16	NEXEN		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/11/2021	Inspection Date)	09/11/2021	
	Survey held at	POON SIANG SEOW				
		No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: