

Claim	S1M03LOK
Reference	CS3/ASM21011422/Gty3e2 
Loss Date	4 November 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	9 Nov 2021 9:21:55 AM
Request Date	9 November 2021
Due Date	
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident PC8863T
 Vehicle
 Registration #

 Make TPVDD

Model

Service Address

'''

Primary Contact/Insured

ONG AUTOMOTIVE
 81 TAGORE LANE, #04-19 TAG A, 787502,
 Singapore

Claim Handler

KOH Janice

janice.kohl@axa.com.sg

Additional Instructions

Messages2 Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2108388.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	8 December 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	8 December 2021

	FAQ	English (SG) ▾	Elaine Kuan ▾		SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	Messages	ence		Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	2 December 2021
	LKKPhotosIn6.pdf.pdf		Evidence		Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	2 December 2021
	AXA Immediate Advice_ TP - PC 8863T.pdf.pdf		Forms / Claim Documents		Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 December 2021
	REPLY FROM TP.msg.msg		Letters and Correspondence		Workshop	KUMAR Shailendra	9 November 2021
	SERVICE CREATED.msg.msg		Letters and Correspondence		Workshop	KUMAR Shailendra	9 November 2021
	PRI TP EMAIL PDF.pdf.pdf		Letters and Correspondence		Workshop	KUMAR Shailendra	9 November 2021
	PRI TP EMAIL.msg.msg		Letters and Correspondence		Workshop	KUMAR Shailendra	9 November 2021