PRS Filed By: GQ REF: CS3/AIG21011425/Gvf3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s STK AUTO

of

Insured: SGH 3383A

Policy No. 1800148982

Claims No. 9670452888SG

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $160k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLS1858T Yr Regn: 12 Sep/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: AUDI Q7 2.0 c.c 1984

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 128924 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ4M8JD005775 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/55R19

R: 255/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 3/11/2021 D.O.I. 09-11-2021

Survey held at W/S 3PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Yes/No BI Involved
20/12/21	Submit DAR

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 20/12/21-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL