

E M SOLUTION PTE LTD

160 Sin Ming Drive #03-18/19, Sin Ming Autocity

Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

Not Authenticated

11 Sep 81150h

3 days

ESTIMATE

Mr **Yeo Wei Khoon**
Blk 48SD Choa Chu Kang Ave 5, #07-144
Singapore 684485

Date : 9th November 2021

Veh No : **SLL 1255U**
Make/Model : **Hyundai Elantra**
Chassis No : KMHD841CMHU309014
Date of Acc : 06.11.21
TP Veh No : SHA 5081H

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Rear Door RH	\$	<i>11</i> 1,285.40 ✓
2	1 pc	Rear Door Weatherstrip RH	\$	<i>11</i> 152.50 X
3	1 pc	Rear Fender RH	\$	<i>11</i> 1,496.30 ✓
4	1 pc	Rear Fender Liner RH	\$	<i>11</i> 228.20 ✓
5	1 pc	Rear Wheel Bearing RH	\$	<i>11</i> 156.10 ✓
6	1 pc	Rear Windscreen Moulding	\$	<i>11</i> 158.20 X
			\$	3,476.70
		Less 20%	\$	695.34
			\$	4,172.04
Special Nett				
7	1 pc	Rear Sport Rim RH	\$	<i>11</i> 450.00 ✓
8	1 set	Rear Fender Liner Clips	\$	<i>11</i> 40.00 X
9	1 pc	Windscreen Sealant	\$	<i>11</i> 40.00 X
		Parts Total :	\$	4,702.04
Labour				
1		To remove & replace upholstery, trim garnishes to facilitate repairs	\$	100.00 <i>501</i>
2		To remove, instal rear windscreen.	\$	<i>11</i> 150.00 X
3		To remove, transfer door components	\$	<i>11</i> 100.00 X
4		To remove, instal/replace rear undercarriage parts.	\$	250.00 <i>501</i>
5		To remove, repair & replace damaged bodyparts and where consistent to the accident.	\$	400.00 <i>3601</i>
6		Putty and respray painting on affected portions.	\$	400.00 ✓
7		Rust proofing on affected portions.	\$	<i>11</i> 80.00 X
		Labour Total :	\$	1,480.00
		Total Parts & Labour :	\$	6,182.04

E M Solution Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: