

*Kenneth*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLL 1255U  
 at Workshop m/s EM  
 of 717A  
 Insured: SHA 5081H  
 Policy No. \_\_\_\_\_  
 Claims No. S1M03LPY  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$53K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 03 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLL 12554 Yr Regn: 02, 17  
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai Elantra cc 1591  
 Colour: M. Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 102314 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMH0841CMHU 309084  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inoper? / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inoper? / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modl: NI / S/Rlm / STD / A/Rlm or \_\_\_\_\_  
 Tyre Size: F: 205/55R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front R/Bal. 9 mm Rear R/Bal. 9 mm  
 L/Bal. 9 mm L/Bal. 9 mm  
 D.O.A. 6/11/21 D.O.I. 10/11/2021  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
O/S Acc  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Confirmed L/S \$1150, 3 repair days. (RED \$5032.04; 81%)

Date/Time, File Pass to?  : Prell. Report  
 1) 18/11 TYPIS  : Final Report  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

Days Of Repair: 3  
 Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation	_____
S - RS	_____
Fees	_____
Others	_____
TOTAL	_____

Report Format: TP  
 Lump Sum H.B.T. (\$ 1150)

# E M SOLUTION PTE LTD

160 Sin Ming Drive #03-18/19, Sin Ming Autocity  
Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

*Not Notified*

*1. P. 1. 1/1/21*


## ESTIMATE

Mr **Yeo Wei Khoon**  
Blk 485D Choa Chu Kang Ave 5, #07-144  
Singapore 684485

Date : 9th November 2021

Veh No : **SLL 1255U**  
Make/Model : **Hyundai Elantra**  
Chassis No : KMHD841CMHU309014  
Date of Acc : **06.11.21**  
TP Veh No : **SHA 5081H**

S/No	Qty	Description	Unit Price	Amount
<b>Materials</b>				
1	1 pc	Rear Door RH		\$ <i>11</i> 1,285.40 <i>X</i>
2	1 pc	Rear Door Weatherstrip RH		\$ <i>12</i> 152.50 <i>X</i>
3	1 pc	Rear Fender RH		\$ <i>11</i> 1,496.30 <i>X</i>
4	1 pc	Rear Fender Liner RH		\$ <i>12</i> 228.20 <i>X</i>
5	1 pc	Rear Wheel Bearing RH		\$ 156.10 <i>?</i>
6	1 pc	Rear Windscreen Moulding		\$ <i>12</i> 158.20 <i>X</i>
				\$ 3,476.70
Less 20%				\$ 695.34
				\$ 4,172.04
<b>Special Nett</b>				
7	1 pc	Rear Sport Rim RH		\$ <i>12</i> 450.00 <i>✓</i>
8	1 set	Rear Fender Liner Clips		\$ <i>12</i> 40.00 <i>X</i>
9	1 pc	Windsceen Sealant		\$ <i>12</i> 40.00 <i>X</i>
Parts Total :				\$ 4,702.04
<b>Labour</b>				
1		To remove & replace upholstery, trim garnishes to facilitate repairs		\$ 100.00 <i>501</i>
2		To remove, instal rear windscreen.		\$ <i>12</i> 150.00 <i>X</i>
3		To remove, transfer door components		\$ <i>12</i> 100.00 <i>X</i>
4		To remove, instal/replace rear undercarriage parts.		\$ 250.00 <i>?</i>
5		To remove, repair & replace damaged bodyparts and where consistent to the accident.		\$ 400.00 <i>3601</i>
6		Putty and respray painting on affected portions.		\$ 400.00 <i>✓</i>
7		Rust proofing on affected portions.		\$ <i>12</i> 80.00 <i>X</i>
Labour Total :				\$ 1,480.00
<b>Total Parts &amp; Labour :</b>				\$ <b>6,182.04</b>

  
\_\_\_\_\_  
E M Solution Pte Ltd

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

for Surveyor

SL0321B80002 / Lal Huat (Meng Kee) Motor Pte Ltd  
ENTRY DATE & TIME: 08/11/2021 13:13 (SGT)  
SUBMITTED BY: LHMK-3  
VERSION: 1 (08/11/2021 13:13 (SGT))

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	08/11/2021 13:13 (SGT)
Date of Accident	06/11/2021 15:10 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	Towards Tuas (before CTE exit)
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL1255U
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Yeo Wei Khoon
NRIC No	S7216717A
Email Address	weikhyeo@gmail.com
Mobile Phone No	(Phone) +65-96733951
Alternative Phone No	+65-96733951

## VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Elantra
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

## INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800001735-03
Cover Note Number	-

## DRIVER

Name of Driver	Yeo Wei Khoon
NRIC No	S7216717A

 Accident report SL0321B80002

Page 1 of 12

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renewate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholders Signature / Date & Time  
Sketch Plan 08 NOV 2021

  
Driver's Signature (If driver is not the policyholder) / Date & Time  
08 NOV 2021

  
Witnessed by Reporting Centre Personnel  
Angle Soh

