

Your Ref: AXA.19.0368.WT.nxy

Date: 24th Dec 2021

Our Ref: CS1/LAW21011461/Gqy3e2

M/s Axa Insurance Pte Ltd

C/o Willy Tay's Chambers

70 Shenton Way

#17-02 Eon Shenton

Singapore 079118

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLN 2036T

INSURED VEHICLE: SHB 7931L

ACCIDENT DATE: 17/10/2017

We thank you for your instruction on 08/11/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLN 2036T from M/s Aeon Auto Consultants LLP.
- b) Survey report by AJAX Inspection Services Pte Ltd.
- c) Final Repair Bill of SLN 2036T from M/s Isafe Garage.
- d) Singapore Accident Statement of Vehicles SLN 2036T and SHB 7931L.
- e) Colour damaged vehicle photographs of SLN 2036T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLN 2036T
Make & Model	: BMW 116D 5DR Hatchback DSC LED
Chassis Number	: WBA1V720505C07384
Year of Registration	: 2016
Engine Capacity	: 1496 cc

- 2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.