

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

10/11/2021 10:59

JOB-NO: 50113750

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880

64739522

VEHICLE DETAILS

LICENSE NO: SHC7291U

TRANS: AUTO

CHASSIS: KMHLB41UMGU093575

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4DFU566587

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO RUST PROOFING OF THE AFFECTED AREA	1.00	160.00	0.00	160.00	X	Y	
2 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	240.00	0.00	240.00	30	Y	
3 TO RESPRAY FRONT DOOR PANEL	1.00	250.00	0.00	250.00	X	210	Y
4 TO RESPRAY FRONT SIDE MIRROR	1.00	250.00	0.00	250.00	80	Y	
5 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	1.00	800.00	0.00	800.00	100	Y	
TOTAL:		1,700.00	0.00	1,700.00			
MATERIALS							
1 FRONT RH SIDE MIRROR ASSY	1.00	586.30	117.26	469.04	L	Y	
2 FRONT RH SIDE MIRROR GLASS	1.00	75.90	15.18	60.72	L	Y	
3 FRONT RH DELTA CHROME GARNISH	1.00	102.30	20.46	81.84	L	Y	
4 FRONT DOOR "COMFORT DELGRO" STICKER	1.00	140.00	0.00	140.00	S	Y	
TOTAL:		904.50	152.90	751.60			
TOTAL PARTS & LABOUR :		2,604.50	152.90	2,451.60			

EXCESS/LOADING: S\$ 0.00

No. Of Day: 2 dys

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: / /

SURVEYED BY:

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

Ding Auto Consultants hence notify

Ding Auto User of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

ESTIMATOR: STA AUTO CENTRE

TEL: Third party survey is on a "FAX" basis

No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

G-STAR-WI-ET-001-02-Rev00