

|   |   |          |   |   |   |   |      |   |   |             |
|---|---|----------|---|---|---|---|------|---|---|-------------|
| ⏪ | < | 1 of 2 ? | > | ⏩ | ↺ | ↻ | 100% | ⏴ | ⏵ | Find   Next |
|---|---|----------|---|---|---|---|------|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                        |                                                                                                           |                        |                                                                |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|------------------------|----------------------------------------------------------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                               |                                                                                                           |                        |                                                                |  |
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705                                              |                                                                                                           |                        | Ref: CS3/SMR21010568/Euf3e2-1<br>Date: 16/11/2021<br>Code: SMR |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                           |                        |                                                                |  |
| <b>Insured Veh.</b>                                                                                                                    | SHD 6298C                                                                                                 | <b>Veh. Inspected</b>  | GBB 7743J                                                      |  |
| <b>Policy No.</b>                                                                                                                      |                                                                                                           | <b>Coverage (\$)</b>   | 0.00                                                           |  |
| <b>Claim No.</b>                                                                                                                       | TAX/10/21/2004                                                                                            | <b>Excess (\$)</b>     | 0.00                                                           |  |
| <b>Assign From</b>                                                                                                                     | ANA MAGNAYE                                                                                               | <b>Assign Date</b>     | 10/11/2021                                                     |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                           |                        |                                                                |  |
| <b>Make &amp; Model</b>                                                                                                                | TOYOTA DYNA 150                                                                                           | <b>c.c</b>             | 2982                                                           |  |
| <b>Engine No.</b>                                                                                                                      | HIDDEN                                                                                                    | <b>Year of Reg.</b>    | 2010                                                           |  |
| <b>Chassis No.</b>                                                                                                                     | JTFAT35Y90K201015                                                                                         | <b>Colour</b>          | WHITE                                                          |  |
| <b>Odometer</b>                                                                                                                        | 442586 KM                                                                                                 | <b>Steering</b>        | IN ORDER                                                       |  |
| <b>Brakes</b>                                                                                                                          | IN ORDER                                                                                                  | <b>Modification</b>    | STANDARD ALLOY RIM                                             |  |
| <b>General</b>                                                                                                                         | FAIR                                                                                                      |                        |                                                                |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                           |                        |                                                                |  |
|                                                                                                                                        | <b>Size</b>                                                                                               | <b>Make</b>            | <b>Balance</b>                                                 |  |
| <b>R/H Front Tyre</b>                                                                                                                  | 155/50 R15                                                                                                | DUNLOP                 | 4 mm                                                           |  |
| <b>L/H Front Tyre</b>                                                                                                                  | 155/50 R15                                                                                                | DUNLOP                 | 4 mm                                                           |  |
| <b>R/H Rear Tyre</b>                                                                                                                   | 155/50 R15                                                                                                | DUNLOP                 | 4 mm                                                           |  |
| <b>L/H Rear Tyre</b>                                                                                                                   | 155/50 R15                                                                                                | DUNLOP                 | 4 mm                                                           |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                           |                        |                                                                |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                                           |                        |                                                                |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                           |                        |                                                                |  |
| <b>Accident Date</b>                                                                                                                   | 03/10/2021                                                                                                | <b>Inspection Date</b> | 14/10/2021                                                     |  |
| <b>Survey held at</b>                                                                                                                  | LENG YONG MOTOR WORKSHOP<br>27-A JURONG PORT ROAD<br>#01-28<br>JTC IND SERVICE CENTRE<br>SINGAPORE 619101 |                        |                                                                |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                           |                        |                                                                |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                           |                        |                                                                |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                           |                        |                                                                |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                           |                        | <b>5 Working Days</b>                                          |  |