

ASS. REC. BY: Tan JiaREF: CS3/169216/1508/11983

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. 1663567675SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 942K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJB1057B Yr Regn: 2015 / Apr.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai 1.2 c.c. 1197Colour: Black A/C: Insured / Std / NI / NASp. Reading: 126899 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SJNFEAT114152367Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17R: 7.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 0 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 11/11/21Survey held at 3 Motor works

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/11/21 Submit DAR.

Date/Time, File Pass to?

☐ : Prel. Report

1) 12/11 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: MER-DAR

Lump Sum / L.B. (P) _____

Days Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Visual end (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

(5) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Consistent (NC)

Rear Portion

Vehicle No: **SJB1057B**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	de	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	de	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	de	✓	
1146	992341	Rear Bumper Clips	nc	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	7		
1149	993045	Rear Bumper Reinforcement	ht	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	wa	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	wa	✓	2
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	nr	✓	
1159	993327	Rear End Panel	R	✓	
1160	993339	Rear End Panel Top Garnish	de	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	ofa	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	ht	✓	
1182	991328	Tailgate Emblem	nc	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish	de	✓	
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	wa	✓	2
1188	994646	Tailgate Protector			
1189	994676	Tailgate Camera	nc	✓	
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber	nc	✓	
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant	nc	✓	
1197	994629	Tailgate Lock	ht	✓	
1198	994651	Tailgate Rubber	cut	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	wa	✓	

NAC	INC	Item	CON	AC	Qty
202	993784	Spare Tyre Board			
203	994328	Spare Tyre Panel			
204	995065	Spare Tyre <i>Sponge</i>	de	✓	
205	994326	Spare Tyre Lock Screw			
206	993787	Spare Tyre Cover			
207	995323	Triangle Breakdown Sign			
208	990507	CD Changer Assy			
209	990164	Antenna			
210	990534	Centre Exhaust Pipe Assy			
211	990532	Centre Exhaust Mounting			
212	993364	Rear Exhaust Pipe			
213	993357	Rear Exhaust Chrome Pipe			
214	993361	Rear Exhaust Mounting			
215	993358	Rear Exhaust Heat Shield			
216	995223	Rear LH Chassis Member			
217	993165	Rear RH Chassis Member			
218	993436	Rear LH Fender			
219	993449	Rear LH Fender Protector			
220	993420	Rear LH Fender Inner Panel			
221	993431	Rear LH Fender Inner Trim			
222	993415	Rear LH Fender Inner Garnish			
223	993425	Rear LH Fender Inner Shield			
224	993621	Rear LH Mudflap			
225	993933	Rear LH Wheel Rim			
226	994025	Rear LH Rim Cover			
227	995065	Rear LH Tyre			
228	993456	Rear RH Fender			
229	993450	Rear RH Fender Protector <i>Arch</i>	de	✓	
230	993420	Rear RH Fender Inner Panel			
231	993431	Rear RH Fender Inner Trim			
232	993415	Rear RH Fender Inner Garnish			
233	993425	Rear RH Fender Inner Shield			
234	993622	Rear RH Mudflap			
235	993934	Rear RH Wheel Rim			
236	994025	Rear RH Rim Cover			
237	995065	Rear RH Tyre			
238	995162	Rear Fender Extension Panel LH			
239	993401	Rear Fender Extension Panel RH			
240	993430	Rear Fender Inner Top Garnish			
241	993673	Rear Fender 1/4 Glass			
242	993452	Rear Fender 1/4 Glass Rubber			
243	993453	Rear Fender 1/4 Glass Sealant			
244	993949	Rear Windscreen Glass			
245	993976	Rear Windscreen Rubber			
246	993961	Rear Windscreen Moulding			
247	993955	Rear Windscreen Sealant			
248	994729	Third Brake Light			
249	993385	Rear Fender Air Grille			
250	992167	Fuel Lid			
251	992168	Fuel Neck			
252	992179	Fuel Tank			
253	992184	Fuel Tank Bracket			
254	992191	Fuel Tank Float			
255	990247	Sticker			

No of Items: _____ Assessor: _____

07 days