

AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

Not Authorized
L/Rep B
Running After Paint

SIM KAN CHENG

c/o 46 Lentor Plain

Singapore 786548

Date: 29/May/17

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: MERCEDE BENZ A200 / SLK 6239 P		
1 pc	rear boot lid <i>BT✓</i>	
1 pc	rear boot lid inner trim <i>?</i>	
1 pc	rear boot emblem 'logo' <i>me</i>	
1 pc	rear tail lamp <i>RR/CD✓</i>	
1 pc	rear exhaust silencer <i>?</i>	
1 pc	rear end panel <i>?</i>	
1 pc	rear end panel garnish <i>?</i>	
1 pc	rear fender <i>?</i>	1,750.00
1 pc	rear fender dust cover <i>pu x</i>	
1 pc	rear fender inner trim <i>?</i>	
1 pc	rear bumper <i>BT/CD✓</i>	1,605.00
1 pc	rear bumper side retainer <i>CD✓</i>	64.00
1 pc	rear bumper park sensor <i>1201</i>	@ 450.00
1 pc	rear bumper tow cover <i>mt ✓</i>	
1 pc	rear bumper lower pad <i>BT✓</i>	
1 pc	rear bumper side garnish <i>?</i>	
1 pc	rear bumper reinforcement <i>?</i>	
1 pc	rear bumper sponge pad <i>?</i>	
1 pc	rear exhaust heat shield <i>?</i>	
1 pc	rear exhaust tip pipe cutter <i>BT✓</i>	
1 pc	rear lower arm <i>?</i>	
1 pc	rear windscreen glass moulding <i>me</i>	
1 pc	rear wheel bearing hub assy <i>?</i>	360.00
1 pc	rear shock absorber <i>?</i>	540.00
1 pc	alloy rim <i>?</i>	980.00
1 pc	front head lamp <i>?</i>	
1 pc	front head lamp grille <i>?</i>	
1 pc	front head lamp lower bracket <i>pu x</i>	
1 pc	front head lamp washer nozzle cover <i>pu x</i>	
1 pc	front bumper <i>pu✓</i>	
2 pcs	front bumper park sensor <i>pu x</i>	
1 pc	front bumper side grille <i>?</i>	
1 pc	front bumper side grille trim <i>?</i>	
1 pc	front bumper reinforcement <i>?</i>	
1 pc	front bumper inner pad <i>?</i>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: