



Service Request Details

Claim

S1M03LRR

Reference

CS3/ASM21011528/Gty3 

Loss Date

8 November 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

9 Nov 2021 8:25:45 PM

Request Date

11 November 2021

Due Date

18 November 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

[Decline Work](#)

Vehicle Information

Incident Vehicle Registration #
SML832Z

Make
TPVD Honda

Model
Shuttle

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages1	Invoices	History	Documents	Assessment	Metrics	Notes
-----------	----------	---------	-----------	------------	---------	-------

Document SubType



 Upload Documents

Already Attached

NAME	 SML832Z TP GIA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	KALE Nagesh
DATE UPLOADED	11 November 2021

NAME	 SHC1221L INSD GIA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	KALE Nagesh
DATE UPLOADED	10 November 2021

NAME	 TP PRI FROM SOLICITOR.pdf.pdf
TYPE	Letters and Correspondence
SUBTYPE	Solicitor / Advocate
AUTHOR	KALE Nagesh
DATE UPLOADED	10 November 2021
