




Service Requests

Messages

Claims



Service Request Details

Claim	S1M03LRR
Reference	CS3/ASM21011528/Gty3e2 
Loss Date	8 November 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	9 Nov 2021 8:25:45 PM
Request Date	11 November 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SML832Z
Vehicle	
Registration #	
Make	TPVD Honda
Model	Shuttle

Service Address

› › ›

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages2	Invoices	History	Documents	Assessment	Metrics	Notes
Add						
REFERENCE #	DESCRIPTION	TOTAL AMOUNT	SUBMITTED	STATUS	PAID DATE	WITHDRAW
AC2108022	Final Invoice	\$107.00	19/11/21 4:49 PM	Waiting for Approval		

Totals

Outstanding Invoices	\$107.00	Rejected and Withdrawn	\$0.00
Payments Made	\$0.00		

Total

\$107.00