

LOT :

Priority : NORMAL / URGENT

Reference No : 4/ABR21011535/RIC Claim No.From (Person) : Joanne Xiong ofABSDate/Time : 5/11/2021

IN OPS : Yes / No DOA:

Ref:

MV : \$

TYPE: M.Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or \_\_\_\_\_

Vehicle No : GBF3839Y D.O.A / As At Nov 2021

Make &amp; Model: \_\_\_\_\_

NEW CAR PRICE: \$

Registration Date: \_\_\_\_\_

MV: \$ 28 Quote by: CKS

COE Expiry Date: \_\_\_\_\_

FS: \$ 24 Date

LTA Total Rebate Amount: (PARF) + (COE) =

SV \$

## Calculation for LTA Rebate:

(a) COE Period: \_\_\_\_\_ X 12 = \_\_\_\_\_ Mths

As At: \_\_\_\_\_

\_\_\_\_\_ = \_\_\_\_\_ Mths

\_\_\_\_\_ = \_\_\_\_\_ Mths

(b) Balance Months : \_\_\_\_\_

(d) Residue COE : QP \_\_\_\_\_ X  $\frac{(b)}{(a)}$  = \_\_\_\_\_

(a) \_\_\_\_\_ - (b) \_\_\_\_\_ = \_\_\_\_\_ / 12 = \_\_\_\_\_ &lt; \_\_\_\_\_ yrs

Register Before/After MAY 2002

(e) PARF = (OMV) \_\_\_\_\_ X \_\_\_\_\_ X \_\_\_\_\_ = \_\_\_\_\_

LTA Total Rebate Amount: (d)+(e) \_\_\_\_\_

Salvage Value(LTA Rebate - 5%): \_\_\_\_\_

## Calculation for Valuation:

Average MV \_\_\_\_\_ \$

## Calculation for Repossessed vehicle:

High demand vehicle: Yes / No - \$

Parallel Import vehicle: Yes / No - \$

More than 10yrs old: Yes / No - \$

MV for Repossessed vehicle = \$

Engine Capacity: High / Low - \$

Europe / Asia Car - \$

Car Condition: Good/Fair/Poor/Burnt - \$

No. of transfer : - \$

Other deduction - \$

Forced Sales Value derived = \$

Date / Time

Action / Instruction

Additional Information:

GBF3839Y - X\$150k

**Celine Fong (LKKAUTO)**

---

**From:** joanne@absfinancial.sg  
**Sent:** Friday, 5 November 2021 1:44 PM  
**To:** Celine Fong (LKKAUTO)  
**Cc:** jane@absfinancial.sg  
**Subject:** CHECK VALUATION  
**Attachments:** 3839.pdf; 3388.pdf

Hi Celine,

Pls come 38m penjuru rd to check

Warmest regards,  
**ABS FINANCIAL PTE LTD**  
**Joanne Xiong**  
*Hp Department*  
DID +65 6933 9411  
FAX +65 6456 0678

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	215W
<b>Vehicle Details</b>	
Vehicle No.:	GBF3839Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Nov 2021
Vehicle Make:	CITROEN
Vehicle Model:	DISPATCH 2.0I HDI AT
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	10WAPH0403895
Chassis No.:	VF7XURHHAEZ014763
Maximum Power Output:	-
Open Market Value:	\$27,907.00
Original Registration Date:	15 Jun 2015
First Registration Date:	15 Jun 2015
Transfer Count:	3
Actual ARF Paid:	\$1,396.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Jun 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$52,001.00
COE Rebate Amount:	\$18,430.00
<b>Total Rebate Amount:</b>	<b>\$18,430.00</b>

The information contained herein is correct as at 03 Nov 2021

OK

2277k.

(08/11/13) wef

ASS. REC. BY: lgm

REF:

CV/ABS 210115.35/RIC

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: ABF 38394

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

ABF38394

Yr Regn:

/

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

C.C

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp.Reading

245318

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF7XURHHAE 2014763

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TURADO

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

11/11/21

Survey held at

ABS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )
