

ASS. REC. BY:

REF: ~~CS3/ASM21002239/R1vy3-1~~

Special Instruction:

Surveyor: RASULASSIGNMENT (Office)

11.11.2021

From (Person): WONG WEE FU of AXADate/Time: 17/2/2021 10:00 AM

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLG 7108ZInsured: SKA 287Dat Workshop m/s V-Tech Auto ServiceTel: 9455 7994of No. 2 Soon Lee Road #06 - 04

Policy No:

Claim No: S1M0332P

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12-02-2021

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 17-02-2021 12.28P.MPerson Contacted: WILLIAMVehicle IN ☒ OUT

| Date/Time | Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate |
|-----------|---------------------------------------------------------------------|
|           | SLG 7108Z - <input checked="" type="checkbox"/>                     |
|           | SKA 287D - <input checked="" type="checkbox"/>                      |
| 19/2/21   | Send IA via Smart Claim                                             |
| 19/2/21   | Submit PRS, repair range \$10,000-\$11,000 (17 days)                |