



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21011565/Ktf3n2	Date: 25/11/2021
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJM 5645U	Veh. Inspected	SMG 8863H	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10012370/EE	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	12/11/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	RU11310715	Colour	METALLIC PEARL WHITE	
Odometer	44623 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	3 mm	
L/H Front Tyre	215/60 R16	DUNLOP	3 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	4 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/11/2021	Inspection Date	15/11/2021	
Survey held at	GOLD PERFORMANCE PTE LTD 176 SIN MING DRIVE, #01-14, SIN MING AUTOCARE, SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	