

[Service Requests](#)[Messages](#)[Claims](#)

Service Request Details

Claim	S1M03LXN
Reference	CS3/ASM21011568/Gqy3e2 
Loss Date	10 November 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	11 Nov 2021 2:00:20 PM
Request Date	17 November 2021
Due Date	
Services	Pending verification - Direct

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident

GBG1997G

Vehicle

Registration #

Make

TPVD Nissan

Model

NV350 PANEL VAN 2.5 5MT
5DR EURO V

Service Address

’, ’

Primary Contact/Insured

Settlement

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

Messages2InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2108140.pdf.pdf	Email Sent	Translator expenses	LKK AUTO CONSULTANTS PTE LTD (TP)	25 November 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	25 November 2021
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	25 November 2021
 AXA Immediate Advice - GBG1977G (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 November 2021
 SJ0421BA000F-SHD3247U.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	11 November 2021
 GBG1997G - NOA.pdf.pdf	Letters and Correspondence	Others	KALE Nagesh	11 November 2021
 TP PRI FROM WORKSHOP.pdf.pdf	Letters and Correspondence	Workshop	KALE Nagesh	11 November 2021
 SHD3247U INSD GIA.pdf.pdf	Reports & Statement	GIA Report	KALE Nagesh	11 November 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 GBG1997G TP GIA.pdf.pdf	Reports & Statement	GIA Report	KALE Nagesh	11 November 2021