

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21011580/T1VY3E2

**Date:** 07/04/2022

### REFERENCE

Insured/Claimant: LEMONCOOL AIRCON Policy No: DMCVSNW00060312101

Date of Loss: 06/11/2021

Nature of Claim: OD

Claim No: SNM21D206391/C01/CHNGPW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH4139S**

Make & Model: NISSAN NV200, 1.6 DX-2 (A)

Reg. Date: 30/05/2018 (Man. Year: 2018)

Colour: Silver

Engine Capacity: 1597 cc

Market Value/New Car Price: S\$42,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: HR16116630D

Chassis No: VM20122069

Odometer: 108390 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 175/70R14

Rear Tyre Size: 175/70R14

Front Left Side: Lanvigaton 6 mm

Rear Left Side: Lanvigaton 6 mm

Front Right Side: Lanvigaton 6 mm

Rear Right Side: Lanvigaton 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,325.00	5,660.00	665.00	10.51
Miscellaneous Items	155.00	155.00	0.00	0.00
Labour	1,346.79	1,317.05	29.74	2.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,826.79</b>	<b>7,132.05</b>	<b>694.74</b>	<b>8.88</b>
<b>- Excess (S\$)</b>	<b>450.00</b>	<b>450.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>7,376.79</b>	<b>6,682.05</b>	<b>694.74</b>	<b>9.42</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>516.38</b>	<b>467.74</b>	<b>48.64</b>	<b>9.42</b>
<b>Nett Amount (S\$)</b>	<b>7,893.17</b>	<b>7,149.79</b>	<b>743.38</b>	<b>9.42</b>

### INSPECTION

Date of Assignment: 12/11/2021 Present Location: Car City Auto Centre Pte Ltd (HQ)  
Car City Auto Centre Pte Ltd (HQ)  
Date Inspected: 12/11/2021 Inspected At: Blk 9006 #01-198, Tampines Street 93  
Singapore 528840  
Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Apr 2022)	
Parts:	N/A	NISSAN NV200 1.6 DX-2 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH4139S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		6,325.00 F	*5,660.00 F
F=Franchise part.						
Total Parts (\$\$)					6,325.00	5,660.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	155.00	155.00
Sub Total (\$\$)			155.00	155.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	420.00	357.00
2	SPRAY PAINTING	New	926.79	960.05
Gross Labour Cost (\$\$)			1,346.79	1,317.05

Report was unsubmitted during this print-out.

< END OF ESTIMATES >