

ASS. REG. BY:

REF:

AIG/21011583/KC

Kennerth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

CO/UP/INS/UP RES/LOO RES/EVA/INV/INV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / FR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4-6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGW 89110 Yr Regn: 10, 18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 520i c.c. 1998Colour: M. P. White AG: Insured / Std / NI / NASp. Reading: 02599 T/Radio: Insured / Std / NI / NA

Eng No: _____

C.No: WBAJA120708J20786Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45R18R: 275/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 9/11/21 D.O.I. 12/11/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06483

Vehicle Insured : SMM9127L
Accident Date : 09-Nov-2021

Date : 11-Nov-2021

Our Ref : 021165 (AIG) / SHIJIE

PAGE : 1

CHEN ZHIMING JASON
BLK 497A TAMPINES STREET 45
#10-04
Singapore 520497

NOT Notarized
1. B. 1. 1/1/21

ESTIMATED COST OF REPAIR FOR BMW 520i SGW2911D

1 pc Bootlid
1 pc Bootlid "BMW" emblem
1 pc Bootlid "520i" emblem
1 pc Bootlid weatherstrip
1 pc Bootlid lock
1 pc Bootlid lock power drive
1 pc Bootlid inner trim
1 pc Rear bumper
/ 4 pcs Reverse sensors
1 pc Rear bumper reflector (LH)
1 pc Rear bumper reflector (RH)
1 pc Rear bumper towing cover
1 pc Rear bumper lower garnish
1 pc Rear bumper lower cover
1 pc Rear bumper lower inner part
1 pc Rear bumper inner part
1 pc R bumper low garnish inner pt
1 pc Rear bumper reinforcement
1 pc Rear bumper centre retainer
1 pc Rear bumper side bracket (RH)
1 pc Rear bumper side bracket (LH)
1 pc Rear boot smart opener antenna
1 pc Rear boot smart opener sensor
1 pc Rear end panel
1 pc Rear end panel top garnish
1 pc Rr exhaust tail pipe chrome RH
1 pc Rr exhaust tail pipe chrome LH
1 pc Rear exhaust heatshield

R 1,574.64 ✓
R 110.81 ✓
R 87.48 ✓
R 285.77 X
443.23 ?
851.47 ?
R 443.23 X
R 1,283.04 ✓
@ S\$215.00 m/y 860.00 ✓
R 75.82 X
R 75.82 X
R 59.40 X
R 303.26 ✓
64.80 ?
75.60 ?
108.00 ?
81.00 ?
909.79 ?
128.30 ?
145.80 ?
145.80 ?
116.64 ?
145.00 ?
524.88 ?
192.46 ?
174.96 ?
R 174.96 X
93.31 ?

9,535.27
476.76

9,058.51

Con't Page 2 ...

LKK Auto Consultants hence notify :
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMM9127L

Page : 2

1 pc Rear bumper clips
1 pc Rear number plate and case

60.00 sn ✓
60.00 sn X

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00 7

To putty and spray replaced parts

1,000.00 800

To remove and renew reverse sensor
Wiring charges

50.00 ✓
60.00 201

To apply undersealing

80.00 7

Diagnose, program and reset smart
boot system

380.00 7

Total : S\$11,548.51

=====

Singapore Dollars Eleven Thousand Five Hundred
and Forty Eight and Cents Fifty One Only

is subject to final approval from Insurance Company
• Supplemental items (s) must be reviewed and
• No illegal modifications (s) is allowed
• Third party survey is on a "Without Prejudice" basis
• Parts prices are subject to confirmation
• To display damaged part(s) during survey
• To survey before/after spray painting
the Repairs of the following:

Acknowledged by Repairs

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 09/11/2021 17:36 (SGT)
Date of Accident 09/11/2021 08:05 (SGT)
Exact Location of Accident Bishan Flyover, Singapore
Additional Location Information Towards Lornie Road
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGW2911D

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner Chen Zhiming Jason
NRIC No S1441472Z
Email Address sgweifeng@gmail.com
Mobile Phone No (Phone) +65-98373383
Alternative Phone No +65-98373383

VEHICLE PARTICULARS

Manufacturer BMW
Model 520i
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1998

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPCSNW00219872100
Cover Note Number -

DRIVER

Name of Driver Shanaquan Weifeng

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

09 NOV 2021

Driver's Signature (if driver is not the policyholder) / Date & Time

09 NOV 2021

Witnessed by Reporting Centre Personnel

Angie Soh

A = SGW 2911D

B = SMM 127L

Bishan Flyover towards Lorong Rd

Describe Circumstances of the Accident

On 11 November 2021 at about 8:05 am, I was travelling on Graddell Road towards Lorne Road in my vehicle # 9127111 on the first lane when suddenly a vehicle hit me on my rear bumper 91271. No one was injured and we exchanged particulars.

T.P. claim at Allianz United Auto Pte Ltd


Pls send a copy of report to service@allianz.com

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time
09 NOV 2021


Driver's Signature (If driver is not the policyholder) / Date & Time
09 NOV 2021


Witnessed by Reporting Centre Personnel
Angie Soh