

ASS. REC. BY:

REF:

GAZ/ 210116081K

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1.81

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

9/11/21 Confirmed final by \$2235.00; 5 days with Sandra. (Red 1457.50, 392)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☒

: Final Report

Date/Time, File Return to?

2)

Report Format:

00

Lump Sum / (B): (\$ 2,235.00)

Veh No:

GBJ 67545 Yr Regn: 07, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV350 c.c. 2488

Colour:

Silver A/C: Insured / Std / NI / NA

Sp. Reading

59358 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN/MC2E268 0031293

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: All / S/Rim / STD A/Rim or

Tyre Size:

F: 195R 15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

29/10/21

D.O.I.

7/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NIS body

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$